



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV06424/Han Weili Wendy Reg No/Reg Date SKG235Y / 21/11/201 Date In/Mileage 08/05/2021/ 0 Chassis No JMFXTGA2WJZ000945 Engine No 4B11TR9560 Make/Model MIT/ASX 2.0 CVT 2WD (N06) Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	08/05/2021/ 11:07	QUK	289 / Patrick Lee Kevin	10868		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							675 1800.00
REPLACE FRT ¹ BUMPER, BONNET & AFFECTED AREAS				1-5 X 450			
REPAIR ON FRT RH FENDER							1050.00
E PNT98000							
SPRAY ON FRT ¹ BUMPER, HOOD & FRT RH ¹ FENDER				3 X 350			40 80.00
M SUNDRY							
PERFORM RUST PREVENTION							30.00
A 54900099							
CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM							120.00
A 10028901							
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							240.00
M SUNDRY							
TO APPLY ZERTONA COATING ON AFFECTED AREAS							50.00
M SUNDRY							
TO SUPPLY FRT NUMBER PLATE WITH FRAME				CUT			20 50.00
M SUNDRY							
SUNDRIES							
M HEADLAMP ASSY, RH				1.00	828.00	23.00	637.56
M REINFORCEMENT, FR BUMPER				1.00	53.00	23.00	40.81
M FACE, FR BUMPER				1.00	818.00	23.00	629.86
M GRILLE, FR BUMPER				1.00	206.00	23.00	158.62
M GARNISH, FR BUMPER, RH				1.00	27.00	23.00	20.79
M EXTENSION, FR BUMPER				1.00	192.00	23.00	147.84
M GRILLE ASSY, RADIATOR				1.00	344.00	23.00	264.88
M GARNISH, FR BUMPER SIDE				1.00	123.00	23.00	94.71
M GARNISH, FR BUMPER SIDE				1.00	123.00	23.00	94.71
M COVER, FR BUMPER, RH				1.00	37.00	23.00	28.49
M GARNISH, FR BUMPER SIDE				1.00	77.00	23.00	59.29
M GARNISH, FR BUMPER SIDE				1.00	77.00	23.00	59.29
M COVER, FR BUMPER				1.00	308.00	23.00	237.16
M GROMMET, FUEL FILLER LID PA				5.00	2.00	23.00	7.70
M HOOD				1.00	822.00	23.00	632.94

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV06424/Han Weili Wendy Reg No/Reg Date SKG235Y / 21/11/201 Date In/Mileage 08/05/2021/ 0 Chassis No JMFXTGA2WJZ000945 Engine No 4B11TR9560 Make/Model MIT/ASX 2.0 CVT 2WD (N06) Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	08/05/2021/ 11:07	QUK	289 / Patrick Lee	10868			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	MOULDING,FR WHEEL	ARCH,RH	NN		1.00	132.00	23.00	101.64
M	FENDER,FR RH				1.00	512.00	23.00	394.24

Estimate

SURVEYOR NAME: Steve (LKK)

SURVEYOR SIGNATURE: 10/5/21, 1.00p

DATE: 00-AL AL

REMARKS: Excess - ?

P/P, My Bel say
4 days

Confirm & accepted by LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Authorized signatory and company stamp

7% GST on **Nett** 7,030.53
492.14
Total Payable 7,522.67

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.