

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21005679/AQF3N2**Date:** 18/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100456056-05
Claimant Vehicle No :	SKZ777A	Insured Vehicle No :	SLA6842A
Date of Loss:	07/05/2021	Nature of Claim:	TP
		Claim No:	8334403467SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ777A	Engine No:	20705267B48B20B
Make & Model:	BMW 730LI, 2.0 LED NAV HUD SR (A)	Chassis No:	WBA7E02030G913501
Reg. Date:	27/03/2019 (Man. Year: 2018)	Odometer:	11483 km
Colour:	Black		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45R19	Rear Tyre Size:	245/45R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,155.60	7,107.30	3,048.30	30.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,520.00	430.00	2,090.00	82.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,675.60	7,537.30	5,138.30	40.54
Approved Total (Overridden) (S\$)		6,000.00		
Nett Amount (S\$)	12,675.60	6,000.00	6,675.60	52.66

INSPECTION

Date of Assignment:	10/05/2021	Unimotor Company - Kaki Bukit (HQ) 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) Singapore 417883
Date Inspected:	11/05/2021 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FACE	Torn	2,000.00 FL	*1,950.00 FL
2	2		*FRONT BUMPER SENSOR ASSY	Not Necessary	742.00 FL	*- FL
3	1		*FRONT R/H BUMPER SIDE RETAINER	Not Necessary	89.00 FL	*- FL
4	1		*FRONT R/H BUMPER FOG LAMP COVER GARNISH	Not Necessary	278.00 FL	*- FL
5	1		*FRONT R/H HEADLAMP ASSY	Cut	6,300.00 FL	*5,947.00 FL
6	1		*FRONT R/H HEADLAMP LOWER GARNISH	Not Necessary	233.00 FL	*- FL
7	1		*FRONT R/H FENDER ASSY	Repair	1,350.00 FL	*- FL
8	1		*FRONT R/H FENDER INNER SHIELD	Not Necessary	242.00 FL	*- FL
9	10		*FRONT R/H FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FL	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$)	11,284.00 7,897.00
					- List Item Discount on L Items 10.00/10.00% (\$)	1,128.40 789.70
					Total Parts (\$)	10,155.60 7,107.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISM/REWIRE FRONT DAMAGED PORTION	New	200.00	30.00
2	TO RESET ECU AFTER REPAIR	New	120.00	0.00
3	TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	New	1,000.00	200.00
4	TO SEND VEHICLE FOR WHEEL ALIGHTMENT	New	120.00	0.00
5	TO PUTTY AND RESPRAY DAMAGED PORTION	New	1,000.00	200.00
6	TO SPRAY UNDERCOATING IN REPAIR	New	80.00	0.00
Gross Labour Cost (\$)			2,520.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >