



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJE 7323C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,701.30	558.00
1	REAR BUMPER SIDE RETAINER (RH) (CONSISTENT)	DAMAGED	38.52	38.52
1	SET REAR BUMPER CLIP (CONSISTENT)	NECESSARY	50.00	30.00
1	REAR BUMPER REFLECTOR (RH) (CONSISTENT)	NOT NECESSARY	163.71	-
1	REAR CORNER GARNISH (RH) (CONSISTENT)	DEFORMED	375.57	375.57
1	REAR MUDFLAP (RH) (CONSISTENT)	DEFORMED	129.45	129.45
1	REAR WHEEL ARCH PROTECTOR (RH) (CONSISTENT)	CUT	386.70	185.00
1	REAR FENDER (RH) (CONSISTENT)	TO REPAIR SEE LABOUR	1,533.63	-
1	TAILLAMP (RH) (CONSISTENT)	NOT NECESSARY	423.72	-
1	REAR DOOR (RH) (CONSISTENT)	DENTED	1,811.25	1,120.00
1	REAR DOOR LOWER PROTECTOR (RH) (CONSISTENT)	DEFORMED	203.32	203.32
1	REAR SHOCK ABSORBER (RH) (CONSISTENT)	NOT NECESSARY	356.31	-
1	REAR CONTROL ARM (RH) (CONSISTENT)	BENT	77.04	77.04
1	REAR LOWER ARM (RH) (CONSISTENT)	BENT	616.32	441.00
	LESS 10% DISCOUNT		-786.68	-
	LESS 20% DISCOUNT		-	-631.58
			7,080.16	2,526.32
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR TYRE RIM (RH) (SN) (CONSISTENT)	CUT	580.00	400.00
1	REAR TYRE (RH) (SN) (CONSISTENT)	NOT NECESSARY	220.00	-
			800.00	400.00
<b><u>LABOUR</u></b>				
	TO CONDUCT 4-WHEEL ALIGNMENT (2 TIMES).		160.00	80.00
	TO CHECK REAR ELECTRICAL SYSTEM.		80.00	30.00
	TO REMOVE & REINSTALL RHR TYRE & RIM, & TYRE BALANCING.	NOT NECESSARY	80.00	-
	TO REMOVE & REINSTALL RHR UNDERCARRIAGE.		280.00	150.00
	TO TRANSFER RHR DOOR COMPONENTS FROM OLD DOOR TO NEW DOOR.		150.00	80.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TO REMOVE, CUT, CHANGE & PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER (RH). TO PUTTY AND RESPRAY AFFECTED AREAS.		950.00	400.00
			1,200.00	400.00
			2,900.00	1,140.00
GRAND TOTAL			10,780.16	4,066.32
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00

Report Ref No. CS/ASM21005684/Atce2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.