



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: YU DOMINIC YISHAN			Ref: CS/ASM21005684/Atce2 Date: 27/07/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7998P	Veh. Inspected	SJE 7323C	
Policy No.	VFX/P2419140	Coverage (\$)	0.00	
Claim No.	S1M039EA	Excess (\$)	0.00	
Assign From	YU DOMINIC YISHAN	Assign Date	10/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CRV	c.c	2354	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	RE31101544	Colour	SILVER	
Odometer	250890 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	MICHELIN	6 mm	
L/H Front Tyre	225/65 R17	MICHELIN	6 mm	
R/H Rear Tyre	225/65 R17	MICHELIN	6 mm	
L/H Rear Tyre	225/65 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/05/2021	Inspection Date	11/05/2021	
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	