

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21005686/ERA3Q2**Date:** 03/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070091940
Claimant Vehicle No :	FBS1838U	Insured Vehicle No :	GBB694M
Date of Loss:	28/04/2021	Nature of Claim:	TP
		Claim No:	5121290807SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBS1838U	Engine No:	G3K9E0034791
Make & Model:	YAMAHA MT-15, 155cc	Chassis No:	MH3RG5610LK008877
Reg. Date:	03/02/2021 (Man. Year: 2020)	Odometer:	4785 km
Colour:	White		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70-17	Rear Tyre Size:	140/70-17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,792.00	1,039.50	752.50	41.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	250.00	200.00	50.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,042.00	1,239.50	802.50	39.30
+ GST 7.00/7.00% (S\$)	142.94	86.77	56.17	39.30
Nett Amount (S\$)	2,184.94	1,326.27	858.67	39.30
+ Loss of Use (3.0 x S\$30.00/day) (S\$)		90.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,423.72		

INSPECTION

Date of Assignment:	11/05/2021	A.S. Phoon Pte Ltd (Toh Guan)
Date Inspected:	11/05/2021 Inspected At:	Blk 36 Toh Guan Road, East Enterprise Hub #01-35
Estimated Period of Repair:	3.0 days	Singapore 608580

Adjuster: CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*P-PLATE	Cut	18.00 F	*18.00 FL
2	1		*FRONT FENDER	Broken	85.00 F	*85.00 FL
3	1		*FRONT WHEEL	Cut	340.00 F	*340.00 FL
4	2		*FRONT WHEEL BEARING	Necessary	40.00 F	*40.00 FL
5	2		*FRONT WHEEL DUST COVER	Necessary	16.00 F	*16.00 FL
6	1		*FRONT FORK LH	Bent	350.00 F	*350.00 FL
7	1		*FRONT TYRE (80%)	Torn	160.00 F	*128.00 FL
8	1		*HEADLAMP COVER CENTRE	Cut	48.00 F	*48.00 FL
9	1		*HEADLAMP COVER B	Cut	75.00 F	*75.00 FL
10	1		*HEADLAMP COVER LOWER	Cut	55.00 F	*55.00 FL
11	1		*HEADLAMP ASSY	Not Necessary	320.00 F	*- FL
12	1		*PILOT LIGHT	Not Necessary	180.00 F	*- FL
13	1		*STAY ,HEADLAMP	Not Necessary	60.00 F	*- FL
14	1		*SIDE MIRROR	Not Necessary	45.00 F	*- FL

F=Franchise part. L=ListItemDisc.

	Sub Total (\$)	1,792.00	1,155.00
- List Item Discount on L Items 0.00/10.00% (\$)		0.00	115.50
	Total Parts (\$)	1,792.00	1,039.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WORKMANSHIP	New	250.00	200.00
Gross Labour Cost (\$\$)			250.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >