

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21005688/ATF3N2**Date:** 24/08/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00191882000

Claimant Vehicle No : SJM6183D **Insured Vehicle No :** SKW9679G

Date of Loss: 07/05/2021 Nature of Claim: TP Claim No: SNM21D202677/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJM6183D**

Make & Model: SUZUKI SWIFT, 1.5 (A) Engine No: M15A1327724

Reg. Date: 12/01/2009 (Man. Year: 2008) Chassis No: JSAEZC21S00419896

Colour: Red Odometer: 181726 km

Engine Capacity: 1490 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55R15 Rear Tyre Size: 195/55R15

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,222.64	4,313.97	1,908.67	30.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,160.00	1,690.00	1,470.00	46.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,382.64	6,003.97	3,378.67	36.01
Approved Total (Overridden) (\$\$)		4,800.00		
(\$\$)	9,382.64	4,800.00	4,582.64	48.84
+ GST 7.00/7.00% (\$\$)	656.78	336.00	320.78	48.84
Nett Amount (\$\$)	10,039.42	5,136.00	4,903.42	48.84

INSPECTION

Date of Assignment: 10/05/2021

Date Inspected: 11/05/2021 Inspected At: Twincar Automotive Pte Ltd (Kaki Bukit)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
AUTOHUB
Singapore 417921

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2021)
Parts:	144	SUZUKI SWIFT 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM6183D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	607.20 FL	*607.20 FL
2	2		*REAR BUMPER BRACKET L/R	Dented	73.40 FL	*73.40 FL
3	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	46.20 FL	*46.20 FL
4	1		*REAR END PANEL	Dented	316.70 FL	*316.70 FL
5	1		*REAR END PANEL AIR VENT	Deformed	29.60 FL	*29.60 FL
6	1		*REAR END PANEL INNER TOP GARNISH	Deformed	91.00 FL	*91.00 FL
7	2		*REAR NUMBER PLATE LAMP L/R	Not Necessary	60.40 FL	*- FL
8	1		*REAR TAILGATE	Repair	690.25 FL	*- FL
9	1		*REAR TAILGATE LOGO EMBLEM	Necessary	48.00 FL	*48.00 FL
10	1		*REAR TAILGATE SWIFT EMBLEM	Necessary	26.10 FL	*26.10 FL
11	1		*REAR TAILGATE LOCK	Not Necessary	150.05 FL	*- FL
12	1		*REAR TAILGATE OUTER HANDLE GARNISH	Not Necessary	57.45 FL	*- FL
13	2		*REAR TAILGATE RUBBER GUIDE STOPPER	Not Necessary	19.60 FL	*- FL
14	1		*REAR TAILGATE WEATHER STRIP SEAL	Not Necessary	96.65 FL	*- FL
15	2		*REAR TAILLAMP L/R	Cracked	672.86 FL	*490.00 FL
16	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
17	1		*REAR BUMPER LOWER SPOILER	Deformed	800.00 FS	*750.00 FS
18	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
19	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
20	1		*REAR EXHAUST SILENCER BOX	Damaged	1,500.00 FS	*1,300.00 FS
21	1		*REAR EXHAUST SILENCER GASKET	Necessary	60.00 FS	*30.00 FS
22	2		*REAR EXHAUST SILENCER RUBBER MOUNTING	Not Necessary	80.00 FS	*- FS
23	1		*REAR NUMBER PLATE	Dented	25.00 FS	*25.00 FS
24	1		*REAR NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS
25	1		*REAR REVERSE CAMERA	Damaged	700.00 FS	*450.00 FS
26	1		*SET REAR TAILGATE INNER TRIM GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
27	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Not Necessary	60.00 FS	*- FS
28	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	40.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,670.46	4,573.20
- List Item Discount on L Items 15.00/15.00% (\$\$)	447.82	259.23
Total Parts (\$\$)	6,222.64	4,313.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	60.00	60.00
2	TO REMOVE,REINSTALL TAILGATE WINDSCREEN	New	150.00	0.00
3	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR)	New	120.00	60.00
4	TO RE-SPRAY PAINTING ON THE REAR BOOTLID,REAR END PANEL,REAR FENDER (L/R),SPARE TYRE PANEL AND REAR BUMPER	New	1,400.00	800.00
5	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	150.00	60.00
6	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	650.00
7	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	60.00
Gross Labour Cost (\$\$)			3,160.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >