

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21005690/KTF3Q2
Date: 29/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SLS4132J	Insured Vehicle No :	SKT5588C
Date of Loss:	05/05/2021	Nature of Claim:	TP
		Claim No:	8026409340SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS4132J	Engine No:	2ZR8169891
Make & Model:	HONDA ACCORD, 1.6 (M)	Chassis No:	ZYX102065283
Reg. Date:	22/09/2017 (Man. Year: 2017)	Odometer:	305526 km
Colour:	Metallic Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Nexen 8 mm	Rear Left Side:	Roadstone 8 mm
Front Right Side:	Nexen 8 mm	Rear Right Side:	Roadstone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,778.13	13,112.70	4,665.43	26.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,110.00	2,510.00	1,600.00	38.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,888.13	15,622.70	6,265.43	28.62
Approved Total (Overridden) (S\$)		12,500.00		

Nett Amount (S\$)**21,888.13****12,500.00****9,388.13****42.89****INSPECTION**

Date of Assignment: 10/05/2021

Date Inspected: 19/05/2021

Inspected At:

BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569541.
Repairer:Lian Her Motors (HQ)

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	1,260.40 FL	*1,128.00 FL
2	1		*FRONT BONNET LOCK	Distorted	105.60 FL	*105.60 FL
3	2		*FRONT HEADLAMP ASSY	N/S Cut / O/S Mtg Cracked	3,608.60 FL	*3,608.60 FL
4	1		*FRONT GRILLE	Mtg Cracked	434.80 FL	*434.80 FL
5	1		*FRONT GRILLE EMBLEM	Cracked	1,550.20 FL	*1,550.20 FL
6	1		*FRONT BUMPER	Cracked	985.60 FL	*794.20 FL
7	1		*FRONT BUMPER UPPER REINFORCEMENT	Bent	461.60 FL	*461.60 FL
8	1		*FRONT BUMPER UPPER REINFORCEMENT SPONGE	Cracked	95.20 FL	*95.20 FL
9	2		*FRONT BUMPER UPPER REINFORCEMENT BRACKET	Repair	610.20 FL	*- FL
10	1		*FRONT BUMPER LOWER REINFORCEMENT	Repair	273.10 FL	*- FL
11	1		*FRONT BUMPER LOWER REINFORCEMENT SPONGE	Cracked	75.80 FL	*75.80 FL
12	2		*FRONT BUMPER LOWER REINFORCEMENT BRACKET	Repair	289.20 FL	*- FL
13	1		*FRONT LOWER BUMPER	Mtg Cracked	499.30 FL	*439.60 FL
14	1		*FRONT LOWER GRILLE	Cracked	154.70 FL	*98.50 FL
15	2		*FRONT BUMPER SIDE RETAINER	Serviceable	190.20 FL	*- FL
16	1		*FRONT NO PLATE HOLDER	Serviceable	122.80 FL	*- FL
17	1		*REAR TAIL-GATE ASSY	Bent	1,250.60 FL	*1,198.30 FL
18	1		*REAR TAIL-GATE GLASS MOULDING	Necessary	95.20 FL	*95.20 FL
19	1		*REAR TAIL-GATE INNER TRIM BOARD	Mtg Cracked	426.50 FL	*385.20 FL
20	1		*REAR TAIL-GATE REFLECTOR	N/S Mtg Cracked/O/SServiceable	1,244.48 FL	*395.10 FL
21	1		*REAR TAIL-GATE OUTER GARNISH	Mtg Cracked	925.60 FL	*925.60 FL
22	1		*REAR TAIL-GATE INNER LOCK	Dented	452.70 FL	*361.60 FL
23	1		*REAR TAIL-GATE EMBLEM -HYBRID	Necessary	48.90 FL	*48.90 FL
24	1		*REAR TAIL-GATE EMBLEM -C-HR	Necessary	45.80 FL	*45.80 FL
25	1		*REAR TAIL-GATE EMBLEM	Necessary	62.30 FL	*62.30 FL
26	1		*REAR BOOT RUBBER	Serviceable	205.60 FL	*- FL
27	1		*REAR BUMPER	Buckled	985.10 FL	*855.10 FL
28	1		*REAR BUMPER REINFORCEMENT	Bent	483.20 FL	*393.20 FL
29	2		*REAR BUMPER REFLECTOR GARNISH	Serviceable	251.20 FL	*- FL
30	2		*REAR BUMPER REFLECTOR	Serviceable	290.20 FL	*- FL
31	1		*REAR LOWER BUMPER	Cracked	655.70 FL	*465.70 FL
32	2		*REAR BUMPER SIDE RETAINER	Serviceable	150.20 FL	*- FL
33	1		*REAR TOW COVER	Dented	55.10 FL	*55.10 FL
34	1		*REAR BUZZER	Serviceable	175.20 FL	*- FL
35	2		*REAR FENDER ARCH GARNISH	Serviceable	330.40 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR END PANEL	Bent	725.70 FL	*725.70 FL
37	1		*REAR END PANEL INNER GARNISH	Mtg Cracked	402.10 FL	*246.80 FL
38	1		*FRONT SUPPORT TOP PANEL	Buckled	372.60 FL	*372.60 FL
39	2		*FRONT SUPPORT SIDE BEAM	Repair	310.20 FL	*- FL
40	1		*FRONT SUPPORT LOWER MEMBER	Repair	285.10 FL	*- FL
41	2		*FRONT HEADLAMP PANEL	Repair	430.20 FL	*- FL
42	1		*FRONT BRACE PANEL	Bent	155.70 FL	*155.70 FL
43	1		*FRONT GRILLE BEAM	Distorted	205.10 FL	*205.10 FL
44	1		*AIR CON CONDENSER	Bent	1,486.20 FL	*1,218.50 FL
45	20		*REAR BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
46	1		*REAR REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
47	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
48	1		*REAR NO PLATE	Cracked	40.00 FS	*40.00 FS
49	1		*FRONT NO PLATE	Dented	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,584.18	17,363.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,806.05	4,250.90
Total Parts (\$\$)	17,778.13	13,112.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE /RENEW THE ABOVE PARTS INCLUDING KNOCKING ,WELDING & CUTTING	New	1,600.00	1,100.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	1,600.00	1,000.00
3	CHECK AND RECONNECT WIRING	New	40.00	40.00
4	TO ANTI-RUST COATING	New	150.00	90.00
5	REMOVE/REFIT REAR WINDSCREEN	New	120.00	120.00
6	REMOVE /REFIT REAR BOOT UPHOLSTERY	New	120.00	60.00
7	REMOVE/RENEW FRONT COLLISION SENSOR AND TO RESET TO FACTORY SPECIFICATION	New	280.00	0.00
8	REMOVE/RENEW AIR CON CONDENSER & TO TOP UP GAS	New	200.00	100.00
Gross Labour Cost (S\$)			4,110.00	2,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >