

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21005692/NGS3Q2
Date: 15/12/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070125282
Claimant Vehicle No :	SMY7474J	Insured Vehicle No :	SMU7467B
Date of Loss:	08/05/2021	Nature of Claim:	TP
		Claim No:	3669592891SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY7474J		
Make & Model:	HONDA ACCORD, 1.6 (M)	Engine No:	CEH002025
Reg. Date:	20/01/2009 (Man. Year: 2009)	Chassis No:	ZHWGE54T19LA08583
Colour:	Red	Odometer:	86635 km
Engine Capacity:	5204 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	295/30 R19	Rear Tyre Size:	295/30 R19
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	Pirelli 4 mm	Rear Right Side:	Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

12/15/21, 12:04 PM

Adjuster Report

Date of Assignment: 10/05/2021

Date Inspected: 11/05/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Zoom Autowerks Pte Ltd (HQ)
15 Kaki Bukit Road 4, #01-53
Singapore 417808

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE:\$255,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	0.00 F	*- F
2	1		*REAR BUMPER GRILLE	Cracked	0.00 F	*- F
3	10		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	Repair	0.00 F	*- F
5	1		*REAR END PANEL	Repair	0.00 F	*- F
6	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
7	2		*REAR EXHAUST CHROME PIPE RH	Bent	0.00 F	*- F
8	1		*REAR EXHAUST HEAT SHIELD	Distorted	0.00 F	*- F
9	1		*REAR RH FENDER	Repair	0.00 F	*- F
10	1		*REAR RH FENDER INNER SHIELD RH	Cracked	0.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	0.00
						0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >