

The insurer has given adjuster a maximum mandate of S\$25,000.00 to authorize directly on their behalf, but the adjuster has disabled direct offer mode.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21005695/NVF3E2
Date: 22/09/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29149972ATM
Claimant Vehicle No :	SMH6559U	Insured Vehicle No :	SLX2656B
Date of Loss:	23/04/2021	Nature of Claim:	TP
		Claim No:	635488

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH6559U	Engine No:	CAX491000
Make & Model:	VOLKSWAGEN JETTA TSI, 1.4 (A)	Chassis No:	WVWZZZ1KZAM112895
Reg. Date:	01/06/2010 (Man. Year: 2010)	Odometer:	206443 km
Colour:	Silver		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 4 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	Nexen 4 mm	Rear Right Side:	Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,930.47	8,244.51	5,685.96	40.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,820.00	1,360.00	2,460.00	64.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,750.47	9,604.51	8,145.96	45.89
Approved Total (Overridden) (S\$)		7,650.00		
(S\$)	17,750.47	7,650.00	10,100.47	56.90
+ GST 7.00/7.00% (S\$)	1,242.53	535.50	707.03	56.90
Nett Amount (S\$)	18,993.00	8,185.50	10,807.50	56.90

INSPECTION

Date of Assignment:	10/05/2021	
Date Inspected:	11/05/2021	Inspected At: RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Sep 2021)
Parts:	143	VOLKSWAGEN JETTA TSI 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH6559U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	1,770.00 FL	*1,400.00 FL
2	1		*BOOT LID LOGO	Necessary	154.80 FL	*154.80 FL
3	1		*BOOT LID EMBLEM (JETTA)	Necessary	133.30 FL	*133.30 FL
4	1		*BOOT LID EMBLEM (T6I)	Necessary	89.00 FL	*89.00 FL
5	1		*BOOT LID LAMP	N/S Serviceable / O/S Cracked	834.00 FL	*417.00 FL
6	2		*BOOT LID CAR PLATE LAMP	Serviceable	196.00 FL	*- FL
7	1		*BOOT LID INNER LOCK	Serviceable	445.90 FL	*- FL
8	1		*BOOT LID LOCK CATCH	Serviceable	74.50 FL	*- FL
9	1		*BOOT LID WEATHERSTRIP	Torn	298.80 FL	*298.80 FL
10	1		*TAILLAMP	N/S Serviceable / O/S Cracked	1,376.80 FL	*550.00 FL
11	2		*TAILLAMP LOWER BRACKET	Serviceable	134.40 FL	*- FL
12	2		*TAILLAMP BOTTOM RETAINER	Serviceable	218.00 FL	*- FL
13	1		*REAR BUMPER	Cracked	1,377.30 FL	*1,100.00 FL
14	2		*REAR BUMPER SIDE RETAINER	Cracked	240.00 FL	*240.00 FL
15	1		*REAR BUMPER DIFFUSER	Cracked	789.80 FL	*500.00 FL
16	1		*REAR BUMPER CENTER BRACKET	Cracked	185.00 FL	*185.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Serviceable	678.90 FL	*- FL
18	1		*REAR BUMPER UNDER COVER	Cracked	342.00 FL	*250.00 FL
19	1		*REAR BUMPER TOWING COVER	Missing	51.00 FL	*51.00 FL
20	2		*REAR BUMPER REFLECTOR	Serviceable	250.00 FL	*- FL
21	1		*REAR END PANEL	Dented	987.30 FL	*780.00 FL
22	1		*REAR END PANEL TOP GARNISH	Cracked	245.00 FL	*245.00 FL
23	1		*REAR FLOOR PANEL TOP BOARD	Deformed	746.30 FL	*400.00 FL
24	2		*REAR FENDER INNER TRIM	Torn	1,757.20 FL	*900.00 FL
25	1		*REAR EXHAUST PIPE	Dented	1,245.00 FL	*850.00 FL
26	2		*REAR EXHAUST PIPE MOULTING	Serviceable	108.00 FL	*- FL
27	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*60.00 FS
28	1		*REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*50.00 FS
29	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*80.00 FS
30	1		*REAR FENDER INNER TRIM CLIP	Necessary	85.00 FS	*85.00 FS
31	1		*REAR FENDER COWLING CLIP	Not Necessary	50.00 FS	*- FS
32	1		*REVERSE SENSOR	Not Working	350.00 FS	*280.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,403.30	9,098.90
- List Item Discount on L Items 10.00/10.00% (\$)	1,472.83	854.39
Total Parts (\$)	13,930.47	8,244.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	1,500.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,500.00	600.00
3	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS, PERFORM DISTANCE SENSORY TESTING	New	150.00	30.00
4	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUNCTION	New	50.00	30.00
5	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA	New	120.00	0.00
6	DISMENTLE AND RE-INSTALL REAR INTERIOR COMPARTMENT TRIMMING	New	300.00	100.00
7	APPLY TUFF COATING TREATMENT	New	200.00	0.00
Gross Labour Cost (S\$)			3,820.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >