

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21005696/ARA3Q2
Date: 18/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070034784
Claimant Vehicle No :	SDS7088D	Insured Vehicle No :	SMT4290T
Date of Loss:	30/04/2021	Nature of Claim:	TP
		Claim No:	5546430829SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDS7088D		
Make & Model:	HONDA SHUTTLE, 1.5 G CVT ABS (A)	Engine No:	L15B3535517
Reg. Date:	12/08/2016 (Man. Year: 2016)	Chassis No:	GK81004711
Colour:	Black	Odometer:	95286 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,042.24	2,378.80	1,663.44	41.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	970.00	960.00	49.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,972.24	3,348.80	2,623.44	43.93
Approved Total (Overridden) (S\$)		2,650.00		

(S\$)	5,972.24	2,650.00	3,322.24	55.63
+ GST 7.00/7.00% (S\$)	418.06	185.50	232.56	55.63
Nett Amount (S\$)	6,390.30	2,835.50	3,554.80	55.63
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		3,164.50		

INSPECTION

Date of Assignment: 24/05/2021

Date Inspected: 24/05/2021

Inspected At:

Ryder Auto Pte Ltd (HQ)
 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
 Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S HEAD LAMP	Cracked	1,343.00 FL	*1,343.00 FL
2	1		*FRONT N/S FENDER	Repair	543.00 FL	*- FL
3	1		*FRONT N/S TYRE RIM	Cut	1,600.00 FS	*400.00 FS
4	1		*FRONT BUMPER	Deformed	1,050.50 FL	*1,050.50 FL
5	1		*FRONT BUMPER N/S RETAINER	Necessary	71.30 FL	*35.00 FL
6	12		*FRONT BUMPER CLIPS	Necessary	36.00 FS	*36.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,643.80	2,864.50
- List Item Discount on L Items 20.00/20.00% (\$)	601.56	485.70
Total Parts (\$)	4,042.24	2,378.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	800.00	300.00
2	TO SPRAY PAINTING	New	1,000.00	600.00
3	TO REMOVE & REPLACE FRONT N/S RIM	New	80.00	40.00
4	TO CHECK WIRING	New	50.00	30.00
Gross Labour Cost (S\$)			1,930.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >