

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21005698/NQF3E2**Date:** 17/01/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29142447ALM	
Claimant Vehicle No :	SLN1421X	Insured Vehicle No :	SGG1818G	
Date of Loss:	08/05/2021	Nature of Claim:	TP	Claim No: 635834

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN1421X	Engine No:	LEB4729543
Make & Model:	HONDA FIT, 1.5 HYBRID (A)	Chassis No:	GP53321463
Reg. Date:	24/04/2017 (Man. Year: 2016)	Odometer:	84683 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Tourador 4 mm	Rear Left Side:	Tourador 4 mm
Front Right Side:	Tourador 4 mm	Rear Right Side:	Tourador 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,728.72	4,054.72	5,674.00	58.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,290.00	2,170.00	3,120.00	58.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,018.72	6,224.72	8,794.00	58.55
Approved Total (Overridden) (\$\$)		4,430.00		
(\$\$)	15,018.72	4,430.00	10,588.72	70.50
+ GST 7.00/7.00% (\$\$)	1,051.31	310.10	741.21	70.50
Nett Amount (\$\$)	16,070.03	4,740.10	11,329.93	70.50

INSPECTION

Date of Assignment:	11/05/2021	RICO 60 AUTO SERVICES PTE LTD (HQ)
Date Inspected:	11/05/2021 Inspected At:	8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT
Estimated Period of Repair:	5.0 days	Singapore 415875

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Sep 2021)
Parts:	144	HONDA FIT 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN1421X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Dented	998.00 FL	*800.00 FL
2	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	125.00 FL	*125.00 FL
3	1		*TAIL GATE OUTER GARNISH	Cracked	184.00 FL	*184.00 FL
4	1		*TAIL GATE OUTER GARNISH LOGO	Necessary	58.00 FL	*58.00 FL
5	1		*TAIL GATE EMBLEM (FIT)	Necessary	35.00 FL	*35.00 FL
6	1		*TAIL GATE EMBLEM (HYBRID)	Necessary	35.00 FL	*35.00 FL
7	2		*TAIL GATE CAR PLATE LAMP	Serviceable	178.00 FL	*- FL
8	1		*TAIL GATE OPENER HANDLE	Cracked	144.80 FL	*144.80 FL
9	2		*TAIL GATE STOPPER	Serviceable	57.00 FL	*- FL
10	1		*TAIL GATE POCKET HANDLE	Serviceable	54.00 FL	*- FL
11	1		*TAIL GATE INNER TRIM	Cracked	258.00 FL	*258.00 FL
12	1		*TAIL GATE INNER LOCK	Jammed	289.00 FL	*289.00 FL
13	1		*TAIL GATE LOCK CATCH	Not Necessary	46.00 FL	*- FL
14	1		*TAIL GATE WEATHER STRIP	Torn	154.00 FL	*154.00 FL
15	1		*TAIL GATE DETECTOR	Cracked	154.00 FL	*154.00 FL
16	1		*TAIL GATE DETECTOR WIREHARNES	Serviceable	425.00 FL	*- FL
17	2		*TAIL LAMP LED	Serviceable	1,048.00 FL	*- FL
18	1		*REAR BUMPER	Cracked	659.00 FL	*600.00 FL
19	1		*REAR BUMPER SIDE RETAINER	Cracked	65.00 FL	*65.00 FL
20	2		*REAR BUMPER SIDE GRILLE	Cracked	486.40 FL	*486.40 FL
21	1		*END PANEL	Dented	655.00 FL	*550.00 FL
22	1		*END PANEL TOP GARNISH	Deformed	154.00 FL	*154.00 FL
23	1		*REAR ALARM BUZZER	Cracked	188.70 FL	*188.70 FL
24	1		*REAR FLOOR PANEL	Repair	985.00 FL	*- FL
25	1		*REAR FLOOR TOP BOARD	Serviceable	415.00 FL	*- FL
26	1		*REAR FENDER INNER TRIM	O/S Cracked / N/S Serviceable	1,082.00 FL	*300.00 FL
27	2		*REAR FENDER INNER SHIELD	Serviceable	250.00 FL	*- FL
28	1		*REAR EXHAUST TAIL PIPE	Repair	898.00 FL	*- FL
29	1		*REAR EXHAUST HEAD SEAL	Not Necessary	154.00 FL	*- FL
30	2		*REAR EXHAUST MOUNTING	Serviceable	76.00 FL	*- FL
31	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
32	1		*REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
33	1		*TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
34	1		*TAIL GATE SEALANT	Not Necessary	80.00 FS	*- FS
35	1		*TAIL GATE INNER TRIM CLIP	Necessary	50.00 FS	*20.00 FS
36	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	60.00 FS	*50.00 FS
37	1		*TAIL GATE WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
38	1		*REAR FENDER INNER SHIELD CLIP	Serviceable	60.00 FS	*- FS
39	1		*REAR FENDER INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
40	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*30.00 FS
41	1		*REAR FLOOR PANEL INSULATION SEAL	Necessary	150.00 FS	*30.00 FS
42	1		*REVERSE SENSOR	Not Working	220.00 FS	*200.00 FS
43	1		*REVERSE CAMERA	Serviceable	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **11,790.90** **4,970.90**
- List Item Discount on L Items 20.00/20.00% (\$\$) 2,062.18 916.18

Report was unsubmitted during this print-out.

1/17/22, 3:03 PM				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	9,728.72 4,054.72
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	1,500.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	800.00
3	TUFF COAT	New	250.00	100.00
4	WIRING CHECK	New	50.00	30.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	120.00	30.00
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	120.00	30.00
7	REMOVE AND REFIX TAILGATE WINDSCREEN	New	150.00	120.00
8	REMOVE AND REFIX HYBRID BATTERY WITH RESET	New	1,200.00	150.00
9	TRANSFER TAILGATE MECHANISM	New	150.00	50.00
10	CONDUCT WATER LEAKAGE TEST	New	50.00	0.00
11	REMOVE AND REFIX REAR EXHAUST	New	250.00	0.00
12	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	250.00	60.00
Gross Labour Cost (\$\$)			5,290.00	2,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >