

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21005709/UPS3Q2  
**Date:** 30/09/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210002614
<b>Claimant Vehicle No :</b>	SLZ2866B	<b>Insured Vehicle No :</b>	GBF6472B
Date of Loss:	10/05/2021	Nature of Claim:	TP
		Claim No:	5074812712SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLZ2866B</b>	Engine No:	D4FDJH551769
Make & Model:	KIA CARENS, 1.7 D DCT 5DR FWD (A)	Chassis No:	KNAHU815VJ7205521
Reg. Date:	27/04/2018 (Man. Year: 2018)	Odometer:	362761 km
Colour:	Brown		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	DURATURN 6 mm	Rear Left Side:	DURATURN 6 mm
Front Right Side:	DURATURN 6 mm	Rear Right Side:	DURATURN 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	26,287.53	14,937.14	11,350.39	43.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,980.00	4,350.00	2,630.00	37.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>33,267.53</b>	<b>19,287.14</b>	<b>13,980.39</b>	<b>42.02</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>15,400.00</b>		

	(S\$)	33,267.53	15,400.00	17,867.53	53.71
<b>+ GST 7.00/7.00% (S\$)</b>		2,328.73	1,078.00	1,250.73	53.71
<b>Nett Amount (S\$)</b>		<b>35,596.26</b>	<b>16,478.00</b>	<b>19,118.26</b>	<b>53.71</b>
	<b>+ Doc/Search Fee (S\$)</b>		2.00		
	<b>Nett Liability (S\$)</b>		<b>16,480.00</b>		

INSPECTION

Date of Assignment: 11/05/2021

Date Inspected: 11/05/2021

Estimated Period of Repair: 12.0 days

Inspected At:

Tan Lim Motor Pte Ltd (Defu)  
1 Defu Lane 6  
Singapore 539365**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Deformed	627.00 FL	*627.00 FL
2	1		*FRONT BUMPER CENTRE GRILLE	Torn	150.00 FL	*150.00 FL
3	8		*FRONT BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
4	1		*FRONT BUMPER DIFFUSER	Deformed / Torn	167.00 FL	*167.00 FL
5	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	42.00 FL	*- FL
6	2		*FRONT BUMPER FOG LAMP	Not Necessary	372.00 FL	*- FL
7	2		*FRONT BUMPER FOG LAMP TRIM	Not Necessary	236.00 FL	*- FL
8	1		*FRONT BUMPER FOAM	Torn	61.00 FL	*61.00 FL
9	1		*FRONT BUMPER BEAM -TOP	Bent	351.00 FL	*351.00 FL
10	1		*FRONT BUMPER BEAM -BOTTOM	Not Necessary	81.00 FL	*- FL
11	1		*FRONT BUMPER EMBLEM	Necessary	68.00 FL	*68.00 FL
12	1		*FRONT BUMPER TOP RUBBER SEAL	Not Necessary	25.00 FL	*- FL
13	1		*FRONT GRILLE }	Cracked	425.00 FL	*425.00 FL
14	1		*FRONT GRILLE OUTER RING }		85.00 FL	*- FL
15	1		*FRONT GRILLE HOLDER }		45.00 FL	*- FL
16	2		*HEADLAMP	Holder Cracked	3,118.00 FL	*3,116.00 FL
17	2		*HEADLAMP BRACKET	Not Necessary	22.00 FL	*- FL
18	1		*BONNET	Dented / Buckled	831.00 FL	*831.00 FL
19	6		*BONNET INSULATOR CLIPS	Cracked	25.80 FL	*25.80 FL
20	1		*FRONT SUPPORT PANEL	Repair	567.00 FL	*- FL
21	1		*FRONT SUPPORT PANEL TOP GARNISH	Cracked	46.00 FL	*46.00 FL
22	5		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	21.50 FL	*- FL
23	1		*REAR BUMPER	Distorted	452.00 FL	*452.00 FL
24	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
25	1		*REAR BUMPER SIDE RETAINER	O/S Cracked	46.00 FL	*23.00 FL
26	1		*REAR BUMPER LOWER	Distorted	179.00 FL	*179.00 FL
27	1		*REAR BUMPER DEFUSSION	Repair	186.00 FL	*- FL
28	1		*REAR BUMPER BEAM	Cracked	367.00 FL	*341.00 FL
29	1		*REAR BUMPER BEAM BRACKET	O/S Bent	168.00 FL	*84.00 FL
30	1		*REAR BUMPER TOP BRACKET	O/S Bent	50.00 FL	*25.00 FL
31	1		*REAR BUMPER LOWER BRACKET	O/S Bent	81.00 FL	*27.00 FL
32	1		*REAR BUMPER PARKING SENSOR	O/S Torn	640.00 FL	*160.00 FL
33	4		*REAR BUMPER PARKING SENSOR HOLDER	Not Necessary	260.00 FL	*- FL
34	1		*REAR BUMPER REFLECTOR O/S	Broken	116.00 FL	*116.00 FL
35	1		*TAILGATE LID	Badly Dented	1,088.00 FL	*1,088.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*TAILGATE LID REFLECTOR O/S	Broken	773.00 FL	*355.00 FL
37	1		*TAILGATE LID REFLECTOR N/S	Not Necessary	773.00 FL	*- FL
38	1		*TAILGATE LID OUTER GARNISH	Cracked	153.00 FL	*153.00 FL
39	1		*TAILGATE LID CRDI EMBLEM	Necessary	31.00 FL	*31.00 FL
40	1		*TAILGATE LID CAREN EMBLEM	Necessary	28.00 FL	*28.00 FL
41	1		*TAILGATE LID KIA EMBLEM	Necessary	35.00 FL	*35.00 FL
42	1		*REAR WINDSCREEN GLASS	Shattered	1,258.00 FL	*490.00 FL
43	1		*TAILGATE LID OPEN LEVEL	Not Necessary	155.00 FL	*- FL
44	1		*TAILGATE LID NUMBER PLATE LAMP	Not Necessary	78.80 FL	*- FL
45	1		*TAILGATE LID INNER TRIM BOARD	Distorted	153.00 FL	*153.00 FL
46	6		*TAILGATE LID INNER TRIM BOARD CLIPS	Not Necessary	27.00 FL	*- FL
47	1		*TAILGATE LID INNER TRIM BOARD -N/S	Not Necessary	99.80 FL	*- FL
48	1		*TAILGATE LID INNER TRIM BOARD -O/S	Cut	99.80 FL	*99.80 FL
49	6		*TAILGATE LID INNER TRIM BOARD CLIPS -N/S	Not Necessary	27.00 FL	*- FL
50	6		*TAILGATE LID INNER TRIM BOARD CLIPS -O/S	Not Necessary	27.00 FL	*- FL
51	1		*TAILGATE LID INNER TRIM BOARD -TOP	Cut	253.00 FL	*253.00 FL
52	6		*TAILGATE LID INNER TRIM BOARD -TOP CLIPS	Not Necessary	27.00 FL	*- FL
53	1		*REAR WIPER	Not Necessary	85.00 FL	*- FL
54	1		*REAR WIPER MOTOR	Not Necessary	401.00 FL	*- FL
55	1		*TAILGATE LID WEATHERSTRIP	Twisted	115.00 FL	*115.00 FL
56	1		*REAR END PANEL	Badly Dented	611.00 FL	*611.00 FL
57	1		*REAR END PANEL TOP GARNISH	Not Necessary	123.00 FL	*- FL
58	6		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	27.00 FL	*- FL
59	1		*TAILLAMP O/S	Broken	525.00 FL	*357.00 FL
60	4		*TAILLAMP CLIP O/S	Necessary	22.00 FL	*22.00 FL
61	1		*TAILLAMP PANEL O/S	Distorted	155.00 FL	*155.00 FL
62	1		*FLOOR PANEL	Repair	989.00 FL	*- FL
63	1		*FLOOR PANEL BOARD	Not Necessary	515.00 FL	*- FL
64	1		*FLOOR PANEL TOOL COMPARTMENT TREY	Not Necessary	279.00 FL	*- FL
65	1		*O/S REAR SAFETY BELT	Cracked / Jammed	1,389.00 FL	*980.00 FL
66	6		*ROOF LINING CLIPS	Not Necessary	27.00 FL	*- FL
67	1		*O/S REAR 1/4 GLASS WITH OUTER CHROME MOULDING	Bent	334.00 FL	*334.00 FL
68	1		*O/S REAR 1/4 GLASS INNER GARNISH -TOP	Deformed	75.00 FL	*75.00 FL
69	1		*O/S REAR 1/4 GLASS INNER GARNISH -LOWER	Distorted	75.00 FL	*75.00 FL
70	1		*O/S REAR FENDER	Distorted	1,349.00 FL	*1,349.00 FL
71	1		*O/S REAR FENDER INNER COWLING	Torn	202.00 FL	*202.00 FL
72	8		*O/S REAR FENDER INNER COWLING CLIPS	Necessary	44.00 FL	*44.00 FL
73	1		*ROOF TOP LINING	Not Necessary	985.00 FL	*- FL
74	1		*REAR AXLE	Bent / Twisted	1,161.00 FL	*1,160.00 FL
75	1		*REAR AXLE HOUSING	No such part	1,986.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
76	1		*O/S REAR AXLE BRACKET	Not Necessary	85.00 FL	*- FL
77	1		*O/S REAR SHOCK ABSORBER	Not Necessary	200.00 FL	*- FL
78	1		*O/S REAR WHEEL BEARING	Damaged	345.00 FL	*345.00 FL
79	1		*O/S REAR EXHAUST BOX	Not Necessary	811.00 FL	*- FL
80	1		*O/S REAR EXHAUST BOX MOUNTING	Not Necessary	39.00 FL	*- FL
81	1		*FRONT LICENCE PLATE	Bent	50.00 FS	*40.00 FS
82	1		*REAR WINDSCREEN PRIMER	Necessary	40.00 FS	*30.00 FS
83	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	80.00 FS	*30.00 FS
84	1		*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
85	1		*O/S REAR WHEEL SPORT RIM	Bent	450.00 FS	*350.00 FS
86	1		*O/S REAR WHEEL TYRE (60%) (\$200.00) (LOCAL PURCHASE)	Cut	220.00 FS	*120.00 FS
87	1		*O/S REAR 1/4 GLASS SEAL	Necessary	50.00 FS	*40.00 FS
88	1		*O/S REAR 1/4 GLASS SEALANT	Repeated	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>29,091.70</b>	<b>16,524.60</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	2,804.17	1,587.46
<b>Total Parts (\$\$)</b>	<b>26,287.53</b>	<b>14,937.14</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT REAR RIGHT FENDER 1/4 GLASS	New	100.00	60.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	100.00	30.00
3	TO UPHOLSTERY AND MAKE GOOD REPAIR TO CUSHION SEAT AND SEAT FRAME AND RECLINING MECHANISM }	New	200.00	80.00
4	TO DISMANTLE AND REFIT REAR SEAT ,BACKREST ,TRIMMING ,GARNISH ,ROOF -LINING ,SPEAKER SHELFBOARD ,CARPETING AND OTHER TO ENABLE BODY WORK REPAIR }	New	100.00	0.00
5	TO DROP REAR AXLE AND SUSPENSION ASSY ,REMOVE AND RENEWAL OF NECESSARY PARTS ,TO CONDUCT FINAL CHECKING AND TESTING	New	360.00	250.00
6	TO DROP REAR EXHAUST BOX AND RENEW THE SAME	New	100.00	0.00
7	TO PLACE VEHICLE ON JIG BENCJ TO OBTAIN CROSS AND PARALLEL MEASUREMENT AND CORRECT TO MANUFACTURER SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK	New	350.00	0.00
8	TO TRANSFER OF TYRE ,RIM AND ON WHEEL BALANCING	New	50.00	0.00
9	USING ONBOARD SCAN TOOL (OBD) PERFORM FULL ENGINE DIAGNOSTIC CHECK,TO CONFIGURE AND CLEAR ,RESET SRS SERVICE LIGHT	New	250.00	0.00
10	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
11	TO TRANSFER OF TAILGATE FITTINGS ,FIXTURE AND PERFORM WATERSEEPAGE TEST	New	140.00	60.00
12	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	140.00	120.00
13	TO RUST-PROOFING OF THE AFFECTED AREAS	New	300.00	120.00
14	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	120.00	80.00
15	TOWING CHARGES	New	150.00	100.00
16	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,800.00	1,600.00
17	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,600.00	1,800.00
			<b>Gross Labour Cost (\$\$)</b>	<b>6,980.00</b>
				<b>4,350.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >