7/12/2021 Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB21004606/BVF3E2-1

Date: 12/07/2021

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447

**Claimant Vehicle** SJZ9868Z Insured Vehicle No: SMV9852D

No:

Date of Loss: 09/04/2021 Nature of Claim: ΤP Claim No: MFL2021D0001676

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SJZ9868Z

Make & Model: TOYOTA VELLFIRE, 2.4 Z G-Edition (A) 2AZH782559 Engine No: Reg. Date: 18/01/2012 (Man. Year: 2011) Chassis No: ANH208192047 Colour: Odometer: 271030 km Black

**Engine Capacity:** 2362 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18 Front Left Side: Rear Left Side: Bridgestone 5 mm Bridgestone 5 mm Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
9,538.32	3,757.05	5,781.27	60.61
0.00	0.00	0.00	
2,390.00	930.00	1,460.00	61.09
0.00	0.00	0.00	
0.00	0.00	0.00	
11,928.32	4,687.05	7,241.27	60.71
	3,750.00		
11,928.32	3,750.00	8,178.32	68.56
	9,538.32 0.00 2,390.00 0.00 0.00 11,928.32	9,538.32 3,757.05 0.00 0.00 2,390.00 930.00 0.00 0.00 0.00 0.00 11,928.32 4,687.05 3,750.00	9,538.32 3,757.05 5,781.27   0.00 0.00 0.00   2,390.00 930.00 1,460.00   0.00 0.00 0.00   0.00 0.00 0.00   11,928.32 4,687.05 7,241.27   3,750.00

**INSPECTION** 

Date of Assignment: 11/05/2021

T & S MOTOR SERVICE (HQ)

BLK 5035 ANG MO KIO INDUSTRIAL PARK 2 13/04/2021 Inspected At: Date Inspected:

#01-357.

SINGAPORE 569538

Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

7/12/2021 Adjuster Report

### REPAIR DETAILS

## Reference

Version: 1.0 (Last Synchronised: 09 Jul 2021) Part Source: MRM-SG

Parts: M1-MPV TOYOTA VELLFIRE 2.4 Z G-Edition (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJZ9868Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	. Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Dented	2,078.72 FL	*1,567.80 FL
2	1		*FRONT RH DOOR INNER PROTECTOR	Cut	1,061.94 FL	*461.70 FL
3	1		*FRONT RH DOOR INNER TRIM BOARD	Serviceable/Reuse	953.70 FL	*- FL
4	1		*SET FRONT RH DOOR INNER TRIM BOARD CLIPS	Necessary	60.00 FL	*30.00 FL
5	1		*FRONT RH DOOR INNER LOCK	Dented	603.20 FL	*390.40 FL
6	1		*FRONT RH DOOR GLASS REGULATOR	Not Damaged	317.20 FL	*- FL
7	1		*FRONT RH DOOR GLASS REGULATOR MOTOR	Serviceable/Reuse	926.00 FL	*- FL
8	1		*REAR RH SLIDING DOOR	Dented	2,020.60 FL	*1,567.80 FL
9	1		*REAR RH SLIDING DOOR LOWER PROTECTOR	Cut	752.40 FL	*461.70 FL
10	1		*REAR RH SLIDING DOOR INNER TRIM BOARD	Serviceable/Reuse	955.70 FL	*- FL
11	1		*REAR RH SLIDING DOOR INNER TRIM BOARD CLIPS	Necessary	60.00 FL	*30.00 FL
12	1		*REAR RH SLIDING DOOR INNER LOCK	Dented	1,373.40 FL	*500.00 FL
13	1		*REAR RH SLIDING DOOR GLASS REGULATOR	Not Damaged	321.50 FL	*-FL
14	1		*SET REAR RH SLIDING DOOR GLASS REGULATOR MOTOR	Not Damaged	911.70 FL	*- FL
15	1		*REAR RH SLIDING DOOR LOWER ROLLER & BRACKET	Serviceable/Reuse	321.70 FL	*- FL
F=Fra	nchise	part. L=List	ItemDisc.			
				Sub Total (S\$)	12,717.76	5,009.40
			- List Item Discount on L Items	25.00/25.00% (S\$)	3,179.44	1,252.35

**Total Parts (S\$)** 9,538.32 3,757.05

Report was unsubmitted during this print-out.

Adjuster Report

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE, JACK OUT, STRAIGHTEN, PANEL BEATING, ALIGN AND RENEW REPLACED PARTS	New	1,000.00	400.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	New	1,100.00	400.00
3	TO CHECK WIRINGS	New	40.00	20.00
4	TO REMOVE,REFIX FRONT RH & REAR RH SLIDING DOORS FITTINGS	New	150.00	80.00
5	TO SUPPLIED AND APPLIED ANTI RUST TREATMENTS	New	100.00	30.00
	Gross Labour Cost (S\$)		2,390.00	930.00
	Report was unsubmitted during this	s print-out.		

< END OF ESTIMATES >