

# AUTO PERFORMANCE APPRAISAL

APA

VEHICLE SURVEY REPORTS																																
<b>HL Limo Pte Ltd</b> <b>C/O T &amp; S Motor Service</b> <b>Blk 5035 Ang Mo Kio Industrial Park 2</b> <b>#01-357</b> <b>Singapore 569538</b>																																
<b>1</b>	<b>Reference</b> Job Reference No : 21/002295 Claim No : - Claim Type : Third Party Accident Date : 09/04/2021 Survey Date : 13/04/2021 Survey Report Date : 24/04/2021																															
<b>2</b>	<b>Particulars Of Vehicle</b> Vehicle Registration No : SJZ9868Z Make & Model : Toyota Vellfire 2.4Z Vehicle Registration Date : 18/01/2012 Chassis No : ANH208192047 Engine No : Blocked Colour : Black																															
<b>3</b>	<b>Condition Of Vehicle And Tyres</b> <table border="1"><thead><tr><th><u>Mileage (KM)</u></th><th><u>Brakes</u></th><th><u>Steering</u></th><th><u>Modification</u></th></tr></thead><tbody><tr><td>271030</td><td>Serviceable</td><td>Affected</td><td>None</td></tr><tr><th><u>Tyres</u></th><th><u>Make</u></th><th><u>Size</u></th><th><u>Balance (MM)</u></th></tr><tr><td>Front RHS</td><td>Bridgestone</td><td>235/50R18</td><td>5</td></tr><tr><td>Front LHS</td><td>Bridgestone</td><td>235/50R18</td><td>5</td></tr><tr><td>Rear RHS</td><td>Bridgestone</td><td>235/50R18</td><td>6</td></tr><tr><td>Rear LHS</td><td>Bridgestone</td><td>235/50R18</td><td>6</td></tr></tbody></table>				<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>	271030	Serviceable	Affected	None	<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>	Front RHS	Bridgestone	235/50R18	5	Front LHS	Bridgestone	235/50R18	5	Rear RHS	Bridgestone	235/50R18	6	Rear LHS	Bridgestone	235/50R18	6
<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>																													
271030	Serviceable	Affected	None																													
<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>																													
Front RHS	Bridgestone	235/50R18	5																													
Front LHS	Bridgestone	235/50R18	5																													
Rear RHS	Bridgestone	235/50R18	6																													
Rear LHS	Bridgestone	235/50R18	6																													
<b>4</b>	<b>Description Of Damages</b> The vehicle sustained damages at front right hand portion. (For information of damages please refer to Parts/Labour/Photographs attached)																															
<b>5</b>	<b>Instruction</b> This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.																															

# AUTO PERFORMANCE APPRAISAL

## Vehicle Assessment Reports

Annex A

Ref No : 21/002295

### Damage And Repair Cost Adjustment

<u>S/No</u>	<u>Qty</u>	<u>Parts Description</u>	<u>Comments/condition</u>	<u>Workshop Estimate (\$)</u>	<u>Our Assessment (\$)</u>
<u>List Items</u>					
1	1	Front RH door	Dented	2,078.70	2,078.70 DD ✓
2	1	Front RH door lower protector	Deformed/dented	1,061.94	1,061.94 CUT ✓
3	1	Front RH door inner trim board	Serviceable/reuse	953.70	-
4	1 set	Front RH door inner trim board clips	Necessary	60.00	60.00 NEC ✓
5	1	Front RH door inner lock	Bent	603.20	603.20 DD ✓
6	1	Front RH door glass regulator	Bent	317.20	317.20 NDX
7	1	Front RH door glass regulator motor	Serviceable/reuse	926.00	-
8	1	Rear RH sliding door	Buckled	2,020.60	2,020.60 DD ✓
9	1	Rear RH sliding door lower protector	Deformed/dented	752.40	752.40 CUT ✓
10	1	Rear RH sliding door inner trim board	Serviceable/reuse	955.70	-
11	1	Rear RH sliding door inner trim board clips	Necessary	60.00	60.00 NEC ✓
12	1	Rear RH sliding door inner lock	Bent	1,373.40	1,373.40 DD ✓
13	1	Rear RH sliding door glass regulator	Bent	321.50	321.50 NDX
14	1 set	Rear RH sliding door glass regulator motor	Malfunction	911.70	911.70 NDX
15	1	Rear RH sliding door lower roller & bracket	Serviceable/reuse	321.70	-
				12,717.74	9,560.64
Less discount 25%				3,179.44	2,390.16
Total :				9,538.31	7,170.48
Total Spare Parts :				9,538.31	7,170.48

5009.40  
@ 25% 1252.35  
3757.05



# AUTO PERFORMANCE APPRAISAL

## Vehicle Assessment Reports

Annex B

Ref No : 21/002295

### Damage And Repair Cost Adjustment

<u>Items</u>	<u>Job Description</u>	<u>Workshop Estimate (\$)</u>	<u>Adjusted Costs (\$)</u>
1	To remove, jack out, straighten, panel beating, align and renew replaced parts.	1,000.00	<del>600.00</del> 400.00
2	To putty and respray painting on affected areas.	1,100.00	<del>800.00</del> 400.00
3	To check wirings.	40.00	20.00 ✓
4	To remove, refix front RH & rear RH sliding door's fittings.	150.00	<del>120.00</del> 80.00 ✓
5	To supplied and applied anti rust treatments.	100.00	<del>60.00</del> 30.00 ✓
Total Labour :		2,390.00	1,600.00 930.00
Total Spare Parts :		9,538.31	7,170.48
Total Labour :		2,390.00	1,600.00
Total Repair Costs :		11,928.31	8,770.48


### Assessor's Recommendation

Repairer Estimate : 11,928.31  
Our Adjustment : 8,770.48

### Remarks

The repairer has agreed to undertake the repair on a lump sum basis of \$7,250.00, with a repair period of 5 working days.

Surveyed By:

  
Lek Boon Hwee  
Automobile Appraiser

PARTS 3757.05  
LABOUR 930.00  
4687.05  
@20% 937.41  
3749.64

L/S 3750/2  
With 5 repair days

TGLim 8/7/2024