



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2105651

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 11/08/2021
Reference CC6/CTI21005714/Ues3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLV 846T
Insured Veh. SJA 8714Y
Claim No. SNM21D202752/C02
Policy No. DMPCSNW00153912000
Accident Date 10/05/2021
Inspection Date 11/05/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21005714/Ues3q2 Date: 11/08/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJA 8714Y	Veh. Inspected	SLV 846T	
Policy No.	DMPCSNW00153912000	Coverage (\$)	0.00	
Claim No.	SNM21D202752/C02	Excess (\$)	0.00	
Assign From		Assign Date	11/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	PEUGEOT 3008 (A)	c.c	1199	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VF3MRHNYWHS209732	Colour	WHITE	
Odometer	74779 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	CONTINENTAL	7 mm	
L/H Front Tyre	215/60 R17	CONTINENTAL	7 mm	
R/H Rear Tyre	215/60 R17	CONTINENTAL	7 mm	
L/H Rear Tyre	215/60 R17	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/05/2021	Inspection Date	11/05/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 846T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	NOT NECESSARY	2,155.00	-
1	TAILGATE PEUGEOT EMBLEM	NOT NECESSARY	105.00	-
1	TAILGATE 3008 EMBLEM	NOT NECESSARY	102.00	-
1	TAILGATE OUTER GARNISH	NOT NECESSARY	420.00	-
1	TAILGATE INNER LOCK	NOT NECESSARY	388.00	-
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	785.00	-
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	399.00	-
1	TAILGATE WINDSCREEN INNER SEAL	NOT NECESSARY	52.00	-
1	REAR BUMPER	DEFORMED	2,280.00	945.00
2	REAR BUMPER SIDE RETAINERS @\$85.00	NOT NECESSARY	170.00	-
1	REAR BUMPER CHROME MOULDING	SCRATCHED / CRACKED	650.00	410.00
2	REAR BUMPER EXHAUST CHROMES @\$250.00	CRACKED	500.00	310.00
1	REAR BUMPER REINFORCEMENT	DENTED	1,199.00	585.00
2	REAR BUMPER REINFORCEMENT BRACKETS @\$150.00	NOT NECESSARY	300.00	-
1	REAR BUMPER INNER RETAINER	TWISTED / TORN	370.00	366.00
2	REAR BUMPER TOP SIDE COVERS @\$390.00	TO REPAIR SEE LABOUR	780.00	-
2	REAR BUMPER SIDE OUTER PROTECTORS @\$350.00	TORN	700.00	500.00
1	REAR END PANEL	DENTED	1,205.00	805.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	288.00	-
2	TAILLAMPS @\$605.00	NOT NECESSARY	1,210.00	-
	LESS 10% DISCOUNT		-	-392.10
			14,058.00	3,528.90
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	50.00	-
1	SET REAR REVERSE CAMERA (SN)	NOT NECESSARY	380.00	-

Report Ref No. CC6/CTI21005714/Ues3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR LICENCE PLATE W/HOLDER (SN)	NOT NECESSARY	50.00	-
			860.00	100.00
	LABOUR			
	TO CHECK WIRING .		80.00	20.00
	TO DISMANTLE & REPLACING REVERSE CAMERA.	NOT NECESSARY	80.00	-
	TO DISMANTLE & REFIX REVERSE SENSOR .		80.00	50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY .		120.00	80.00
	TO DISMANTLE & REFIX REAR WINDSCREEN .	NOT NECESSARY	150.00	-
	TO TRANSFER TAILGATE MECHANISM .	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING .		100.00	30.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER TOP SIDE COVERS .		1,080.00	600.00
	TO PUTTY & SPRAY PAINTING .		1,500.00	600.00
			3,290.00	1,380.00
GRAND TOTAL			18,208.00	5,008.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CC6/CTI21005714/Ues3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLV 846T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLV 846T

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLV 846T

RE-INSPECTION

