

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 7440R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	DENTED / BUCKLED / WARPED	2,101.40	2,101.40
1	TAILGATE REAR HANDLE (CHROME)	BENT / DISTORTED	353.30	353.30
1	TAILGATE INNER TRIM BOARD	SERVICEABLE	197.70	-
1	TAILGATE INNER LOCK	SERVICEABLE	288.00	-
1	TAILGATE STRIKER	SERVICEABLE	34.40	-
1	TAILGATE DRAUGHT WEATHERSTRIP	ESSENTIAL	135.00	135.00
1	REAR END PANEL (OUTER)	TO REPAIR SEE LABOUR	609.40	-
1	REAR BUMPER	DISTORTED	632.70	632.70
1	REAR BUMPER STEP PANEL	TO REPAIR SEE LABOUR	181.40	-
	LESS 30% DISCOUNT		-	-966.72
			4,533.30	2,255.68
	NETT ITEMS			
1	TAILGATE WINDSCREEN (N)	SERVICEABLE	866.70	-
1	TAILGATE 'NISSAN' MOTIF (N)	ESSENTIAL	48.20	48.20
1	TAILGATE 'NV350' EMBLEM (N)	ESSENTIAL	50.40	50.40
1	TAILGATE 'URVAN' EMBLEM (N)	ESSENTIAL	65.20	65.20
2	TAILGATE STOPPER \$@21.40 (N)	NOT NECESSARY	42.80	-
2	TAILGATE ASSEMBLY @\$228.70 (N)	NOT NECESSARY	457.40	-
2	REAR BUMPER SIDE HOLDER CLIP @\$17.50 (N)	CRACKED	35.00	35.00
	LESS 10% DISCOUNT		-	-19.88
			1,565.70	178.92
	SPECIAL NETT ITEMS			
1	TAILGATE WINDSCREEN SEALANT / REPAIR KIT (SN) }	ESSENTIAL	60.00	40.00
1	TAILGATE WINDSCREEN INNER SEAL / DAM KIT (SN) }	ESSENTIAL	40.00	-
1	TAILGATE '6 PAX' DECAL (SN)	ESSENTIAL	15.00	10.00
1	TAILGATE '70 KM/H' DECAL (SN)	ESSENTIAL	15.00	10.00
1	TAILGATE INNER TRIM BOARD CLIP / FASTENER (SN)	ESSENTIAL	40.00	20.00

Report Ref No. CS3/LPC21002253/R1vf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SET REAR BUMPER CLIP / FASTENER (SN)	ESSENTIAL	50.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	320.00	-
2	TEROSTAT @\$80.00 (SN)	NOT NECESSARY	160.00	-
1	REAR LICENCE PLATE (SN)	SERVICEABLE	18.00	-
			718.00	110.00
	<u>LABOUR</u>			
	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT & CHECK FUNCTIONS INCLUDING TO REPLACE / RECALIBRATE REAR BUMPER REVERSE SENSOR TO SPECIFICATIONS.		80.00	30.00
	TO DISMANTLE / TRANSFER / REBUILD TAILGATE FITTINGS / ANCILLARY ACCESSORIES TO NEW TAILGATE.		150.00	60.00
	TO DISMANTLE / TRANSFER TAILGATE WINDSCREEN TO FACILITATE REPAIRS INCLUDING TO CONDUCT FOR WATER LEAKAGES ETC.		150.00	120.00
	TO DISMANTLE / INSTALL REAR LUGGAGE FITTINGS / ANCILLARY ATTACHMENTS, TRIMS, GARNISHES, SPARE TIRE, TOOLS ETC. TO FACILITATE REPAIRS.		180.00	40.00
	TO DISMANTLE / RENEW THE REAR ACCIDENT DAMAGED PORTIONS. TO HEAT, KNOCK-OUT, RESHAPE, STRAIGHTEN, ORIENTATE, RESTORE & ALIGN REPAIRABLE CONSTITUENTS TO SYMMETRICAL DIMENSIONS. INCLUSIVE OF THE REPAIR OF REAR END PANEL (OUTER) AND REAR BUMPER STEP PANEL.		1,000.00	450.00
	TO PUTTY / PRIMER APPLICATION AND SPRAY PAINTING INCLUDING TOUCH-UP AFFECTED AREAS WITH POLYURETHANE PAINT. }		1,000.00	450.00
	TO DO RUSTPROOFING AND CAVITIES PRESERVATION TO THE REPLACED AND REPAIRED PANELS. }		-	-
			2,560.00	1,150.00
	GRAND TOTAL		9,377.00	3,694.60

RECOMMENDED COST OF LUMP SUM REPAIRS		2,950.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS3/LPC21002253/R1vf3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator