



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
GOH MENG SAN, DAPHNY (WU MINGSHAN) Blk 677b Punggol Drive #06-782 Singapore 822677 Contact No	Cust No/Name	KCV18392/GOH MENG SAN, DAPHNY (WU MINGSH)
	Reg No/Reg Date	SLU475K / 21/11/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AJH000597
	Engine No	3A92UGL9872
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	T06 MED BLUE MICA / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV18392	CRDVCH	11/05/2021/ 13:09	BLC	442 / CocoLu	10920			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E	PNT88000	RENEW FRT FENDER LH, FRT BUMPER, WINDMIRROR LH						1200.00
E	PNT98000	SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH, WINDMIRROR LH						1050.00
A	90000001	CHECK WIRING & ELECTRICAL SYSTEM						30.00
A	10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST						120.00
M	SUNDRY	TRANSFER FRT LEFT RIM						30.00
B	WHEELALIGNMENT	To Conduct Computerize Full Wheel Alignment						120.00
M	SUNDRY	Sundry						20.00
M	FACE,FR BUMPER			1.00	706.00	00.00	706.00	
M	GRILLE,FR UNDER			1.00	165.00	00.00	165.00	
M	GARNISH,FR BUMPER,LH			1.00	127.00	00.00	127.00	
M	BRACKET,FR BUMPER,LH			1.00	13.00	00.00	13.00	
M	FENDER,FR LH			1.00	500.00	00.00	500.00	
M	SHIELD,FR WHEELHOUSE,LH			1.00	98.00	00.00	98.00	
M	MIRROR ASSY,DOOR,LH			1.00	641.00	00.00	641.00	
M	COVER,DOOR MIRROR,OTR LH			1.00	115.00	00.00	115.00	
M	HEADLAMP ASSY,LH			1.00	663.00	00.00	663.00	
M	WHEEL,DISC			1.00	687.00	00.00	687.00	

Confirm & accepted by

	Nett	6,285.00
7% GST on	6285.00	439.95
Total Payable		6,724.95

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.