

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21005726/APS3Q2  
**Date:** 29/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100377809
<b>Claimant Vehicle No :</b>	SKA2206A	<b>Insured Vehicle No :</b>	SKN6047Y
Date of Loss:	09/05/2021	Nature of Claim:	TP
		Claim No:	1731274710SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKA2206A</b>	Engine No:	4A910170418
Make & Model:	MITSUBISHI LANCER, 1.5 MIVEC GLX AT ABS D/AB 2WD 4DR (A)	Chassis No:	JMYSRCY2AAU001865
Reg. Date:	28/01/2011 (Man. Year: 2010)	Odometer:	110938 km
Colour:	Grey		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Windforce 6 mm	Rear Left Side:	Windforce 6 mm
Front Right Side:	Windforce 6 mm	Rear Right Side:	Windforce 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,689.68	2,932.39	4,757.29	61.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,520.00	1,340.00	1,180.00	46.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,209.68</b>	<b>4,272.39</b>	<b>5,937.29</b>	<b>58.15</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,400.00</b>		

<b>Nett Amount (S\$)</b>	<b>10,209.68</b>	<b>3,400.00</b>	<b>6,809.68</b>	<b>66.70</b>
<b>+ Loss of Use (5.0 x S\$60.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,707.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,700.00</b>		

INSPECTION

Date of Assignment: 12/05/2021

Date Inspected: 12/05/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Kt Motorwerk (HQ)  
Blk 3012 Bedok Industrial Park E, #01-2020  
Singapore 489978**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	892.00 FL	*892.00 FL
2	1		*FRONT BUMPER UNDERCOVER	Not Necessary	298.70 FL	*- FL
3	2		*FRONT BUMPER SIDE RETAINERS	O/S Necessary	157.00 FL	*42.00 FL
4	1		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	345.00 FL	*- FL
6	1		*FRONT BUMPER FOG LAMPS COVER RH	Not Necessary	69.70 FL	*- FL
7	1		*HEADLAMP RH	Cut	975.20 FL	*798.00 FL
8	1		*HEADLAMP LOWER RETAINERS RH	Not Necessary	98.70 FL	*- FL
9	1		*SET HEADLAMP CLIPS	Necessary	30.00 FL	*10.00 FL
10	1		*FRONT FENDER RH	Repair	698.70 FL	*- FL
11	1		*FRONT FENDER SIGNAL LAMP RH	Not Necessary	87.50 FL	*- FL
12	1		*FRONT FENDER INNER SHIELD RH	Torn	175.90 FL	*175.90 FL
13	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	30.00 FL	*20.00 FL
14	1		*FRONT WASHER TANK	Deformed	185.60 FL	*81.00 FL
15	1		*FRONT ABSORBER RH	Not Necessary	461.00 FL	*- FL
16	1		*FRONT LOWER ARM RH	Not Necessary	324.00 FL	*- FL
17	1		*FRONT KNUCKLE ARM RH	Not Necessary	398.70 FL	*- FL
18	1		*FRONT STABILIZER LINKAGE RH	Not Necessary	98.20 FL	*- FL
19	1		*FRONT TIE ROD END RH	Not Necessary	86.30 FL	*- FL
20	1		*FRONT WHEEL BEARING RH	Not Necessary	405.20 FL	*- FL
21	1		*FRONT SIDESKIRT RH	Repair	789.60 FL	*- FL
22	1		*FRONT SIDE MIRROR ASSY RH	Cut	598.20 FL	*598.20 FL
23	1		*FRONT SPORT RIM RH	Cut	850.00 FS	*550.00 FS
24	1		*SET FRONT SIDESKIRT CLIPS	Not Necessary	30.00 FS	*- FS
25	1		*FRONT SPORT RIM TYRE LH	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>8,415.20</b>	<b>3,197.10</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	725.52	264.71
<b>Total Parts (\$)</b>	<b>7,689.68</b>	<b>2,932.39</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,000.00	500.00
2	SPRAY PAINTING	New	1,000.00	700.00
3	CHECK WIRING ON HEADLAMP	New	120.00	30.00
4	ANTI RUST	New	80.00	30.00
5	REMOVE AND INSTALL FRONT UNDERCARRIAGE	New	200.00	0.00
6	TO PERFORM COMPUTERIZE WHEEL ALIGNMENT	New	120.00	80.00
			<b>Gross Labour Cost (S\$)</b>	<b>1,340.00</b>
			<b>2,520.00</b>	<b>1,340.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >