



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 6196X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FORK ASSY	BENT / TWISTED	1,150.00	920.00
1	FRONT SPORT RIM	SERVICEABLE	968.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	68.00	-
1	HEADLAMP	SCRATCHED	655.00	485.00
1	FRONT BRAKE DISC	NOT NECESSARY	225.00	-
1	FRONT FENDER	CRACKED	165.00	165.00
1	SET FRONT FAIRING COVER	CUT / CRACKED	1,500.00	980.00
2	SIDE MIRRORS @\$155.00	N/S CUT	310.00	120.00
1	HANDLE BAR	BENT	135.00	135.00
2	HANDLE BAR BALANCERS @\$50.00	N/S SCRATCHED	100.00	40.00
1	HANDLE BAR GRIP	NOT NECESSARY	55.00	-
1	BRAKE LEVER LH	SCRATCHED	150.00	60.00
1	BRAKE LEVER RH	SCRATCHED	150.00	60.00
2	FRONT SIGNAL LAMPS @\$165.00	SERVICEABLE	330.00	-
2	LOWER BELLY PANELS @\$450.00	CUT	900.00	390.00
2	LOWER COWLING CENTRE GRILLES @\$180.00	NOT NECESSARY	360.00	-
2	FOOT STEP GARNISHS @\$185.00	CUT	370.00	370.00
2	FOOT STEPS @\$85.00	NOT NECESSARY	170.00	-
1	REAR EXHAUST	TO REPAIR SEE LABOUR	1,650.00	-
1	REAR EXHAUST FRONT COVER	NOT NECESSARY	65.00	-
1	REAR EXHAUST CENTRE COVER	CUT	99.00	99.00
1	REAR EXHAUST REAR COVER	TO REPAIR SEE LABOUR	60.00	-
1	TAILLAMP	NOT NECESSARY	355.00	-
1	REAR FENDER	DISTORTED	450.00	180.00
1	REAR FENDER BRACKET	BENT	88.00	82.00
1	FRONT INNER CENTRE COVER	NOT NECESSARY	620.00	-
1	FRONT INNER CENTRE OUTER COVER	NOT NECESSARY	350.00	-
1	MAIN STAND	TO REPAIR SEE LABOUR	158.00	-

Report Ref No. CS/AGI21005732/Uqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SIDE STAND	CRACKED / BENT	125.00	125.00
1	FILTER COVER SPORT	CRACKED	250.00	180.00
1	FILTER COVER INNER	CRACKED	255.00	150.00
1	ENGINE CASING	CRACKED	450.00	300.00
1	ENGINE COVER	CUT	350.00	175.00
	LESS 10% DISCOUNT		-	-501.60
			13,086.00	4,514.40
	SPECIAL NETT ITEMS			
1	REAR LICENCE PLATE (SN)	BROKEN	20.00	10.00
1	FRONT LICENCE PLATE (SN)	NECESSARY	20.00	10.00
1	SEAT CUSHION (SN)	TORN	200.00	120.00
			240.00	140.00
	LABOUR			
	TO CHECK WIRING.	NOT NECESSARY	30.00	-
	TO STRAIGHTEN FRONT BODY ALIGNMENT.	NOT NECESSARY	450.00	-
	TO SPRAY PAINTING.		600.00	300.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR EXHAUST,REAR EXHAUST REAR COVER AND MAIN STAND.		500.00	380.00
			1,580.00	680.00
	GRAND TOTAL		14,906.00	5,334.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,200.00

Report Ref No. CS/AGI21005732/Uqf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.