

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21005737/TQF3E2

Date: 10/05/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80480657MCX
Claimant Vehicle No :	SJH7947L	Insured Vehicle No :	SLX2385H
Date of Loss:	08/05/2021	Nature of Claim:	TP
		Claim No:	635858

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH7947L		
Make & Model:	MITSUBISHI LANCER, 1.5 MIVEC GLS 4A/T (A)	Engine No:	4A910105863
Reg. Date:	26/08/2008 (Man. Year: 2008)	Chassis No:	JMYSRCY2A8U008472
Colour:	Pearl White	Odometer:	342422 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,110.10	6,152.10	17,958.00	74.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,700.00	1,900.00	5,800.00	75.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	31,810.10	8,052.10	23,758.00	74.69
Approved Total (Overridden) (\$\$)		6,300.00		
(\$\$)	31,810.10	6,300.00	25,510.10	80.19
+ GST 7.00/7.00% (\$\$)	2,226.71	441.00	1,785.71	80.19
Nett Amount (\$\$)	34,036.81	6,741.00	27,295.81	80.19

INSPECTION

Date of Assignment:	11/05/2021	
Date Inspected:	12/05/2021 Inspected At:	AP Automotive Services Pte Ltd 56 Loyang Way, #04-04 Loyang Enterprise Building Singapore 508775
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 May 2022)

Parts: 143 MITSUBISHI LANCER 1.5 MIVEC GLS 4A/T (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJH7947L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*BOOTLID LAMP L+R	Not Necessary	446.00 FL	*- FL
2	1		*BOOTLID CENTER LAMP	Not Necessary	160.00 FL	*- FL
3	1		*BOOTLID LOCK	Bent	194.00 FL	*194.00 FL
4	1		*BOOTLID LOCK CATCH	Not Necessary	90.00 FL	*- FL
5	1		*BOOTLID WEATHERSTRIP	Cut	215.00 FL	*149.00 FL
6	2		*TAIL LAMP L+R	Cracked	770.00 FL	*770.00 FL
7	2		*TAIL LAMP PANEL L+R	Not Necessary	340.00 FL	*- FL
8	2		*REAR BUMPER RETAINER L+R	Cracked	258.00 FL	*80.00 FL
9	1		*REAR BUMPER REINFORCEMENT BAR	Not Necessary	482.00 FL	*- FL
10	1		*REAR BUMPER SPONGE	Not Necessary	131.00 FL	*- FL
11	1		*REAR WINDSCREEN MOULDING	Not Necessary	149.00 FL	*- FL
12	2		*REAR FENDER L+R	Not Necessary	2,188.00 FL	*- FL
13	2		*REAR FENDER INNER TRIM L+R	Not Necessary	830.00 FL	*- FL
14	2		*REAR FENDER COWLING L+R	Torn	134.00 FL	*134.00 FL
15	1		*END PANEL	Bent	699.00 FL	*407.00 FL
16	1		*END PANEL TOP GARNISH	Deformed	182.00 FL	*140.00 FL
17	1		*SPAREWHEEL PANEL	Repair	983.00 FL	*- FL
18	1		*SPAREWHEEL PANEL TOP BOARD	Cut	238.00 FL	*145.00 FL
19	1		*BOOTLID CARBON FIBRE	Cracked	4,000.00 FS	*1,600.00 FS
20	1		*BOOTLID INNER TRIM	Torn	100.00 FS	*100.00 FS
21	1		*BOOTLID INNER TRIM CLIPS	Necessary	100.00 FS	*10.00 FS
22	1		*TAIL LAMP CLIPS	Necessary	50.00 FS	*20.00 FS
23	1		*TAIL LAMP PANEL SEALANT	Not Necessary	120.00 FS	*- FS
24	1		*REAR BUMPER	Cracked	3,500.00 FS	*1,200.00 FS
25	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
26	1		*SET REAR BUMPER REFLECTOR	Not Necessary	400.00 FS	*- FS
27	1		*SET REAR BUMPER REVERSE SENSOR	Not Working	300.00 FS	*200.00 FS
28	1		*REAR NUMBER PLATE	Cracked	250.00 FS	*45.00 FS
29	1		*REVERSE CAMERA	Distorted	800.00 FS	*250.00 FS
30	2		*REAR FENDER INNER TRIM CLIPS	Not Necessary	200.00 FS	*- FS
31	1		*REAR FENDER COWLING CLIPS	Necessary	200.00 FS	*30.00 FS
32	1		*END PANEL SEALANT	Necessary	250.00 FS	*40.00 FS
33	1		*END PANEL TOP GARNISH CLIPS	Necessary	100.00 FS	*10.00 FS
34	1		*SPAREWHEEL PANEL SEALANT	Not Necessary	300.00 FS	*- FS
35	1		*EXHAUST PIPE	Bent	5,000.00 FS	*600.00 FS
36	1		*EXHAUST GASKET	Not Necessary	100.00 FS	*- FS
37	1		*EXHAUST MOUNTING	Not Necessary	200.00 FS	*- FS
38	1		*EXHAUST HEAT SHIELD	Bent	400.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,959.00	6,354.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	848.90	201.90
Total Parts (\$\$)	24,110.10	6,152.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	2,200.00	800.00
2	SPRAY PAINT ON AFFECTED AREAS	New	2,400.00	800.00
3	TO RNR REAR EXHAUST	New	250.00	80.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION }	New	150.00	30.00
5	TO CHECK WIRING AND BOOTLID LAMP FUNCTION }	New	150.00	0.00
6	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	60.00
7	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	0.00
8	TO RNR UNDERCARRIAGE	New	250.00	0.00
9	TO CHECK WATER LEAK	New	150.00	0.00
10	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
11	TO RNR REAR BOOT MECHANISM	New	350.00	60.00
12	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
13	TO PERFORM RUST PROOFING	New	400.00	40.00
Gross Labour Cost (\$\$)			7,700.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >