

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005740/KGA3Q2**Date:** 10/04/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070017484		
Claimant Vehicle No :	SMU2128M	Insured Vehicle No :	SKK8838J		
Date of Loss:	10/05/2021	Nature of Claim:	TP	Claim No:	1915014217SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU2128M	Engine No:	2ZR2G78682
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Chassis No:	JTDZS3EU30J057625
Reg. Date:	30/07/2020 (Man. Year: 2020)	Odometer:	61503 km
Colour:	Metallic Pearl White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Windforce 7 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Windforce 7 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,161.82	1,030.35	131.47	11.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	420.00	330.00	44.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,911.82	1,450.35	461.47	24.14
+ GST 7.00/7.00% (\$\$)	133.83	101.52	32.31	24.14
Nett Amount (\$\$)	2,045.65	1,551.87	493.78	24.14
+ Car Rental (3.0 x S\$94.00/day) (\$\$)		282.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		1,835.87		

INSPECTION

Date of Assignment:	11/05/2021	
Date Inspected:	12/05/2021	Inspected At: City Auto Pte Ltd (HQ) 160 Sin Ming Drive #05-01,, Sin Ming AutoCity, Singapore 575722
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Dented	556.40 FL	*523.90 FL
2	1		*REAR BUMPER RETAINER	Serviceable	142.80 FL	*- FL
3	1		*REAR BUMPER LOWER DIFFUSER	Dented	849.90 FL	*849.90 FL
					Sub Total (\$)	1,549.10
						1,373.80
					- List Item Discount on L Items 25.00/25.00% (\$)	387.28
						343.45
					Total Parts (\$)	1,161.82
						1,030.35

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS	New	300.00	200.00
2	SPRAY PAINTING ON AFFECTED & REPLACED PARTS	New	450.00	220.00
Gross Labour Cost (S\$)			750.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >