

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21005742/ETF3E2

**Date:** 16/06/2021

### REFERENCE

Insured/Claimant:	TAN KOK SIONG	Policy No:	1900100389		
Date of Loss:	11/05/2021	Nature of Claim:	OD	Claim No:	4702743696SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML7583X	Engine No:	G4FGKH737213
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF1416MK5044407
Reg. Date:	03/06/2019 (Man. Year: 2018)	Odometer:	32106 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$74,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 4 mm	Rear Left Side:	Nexen 4 mm
Front Right Side:	Nexen 4 mm	Rear Right Side:	Nexen 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,845.20	1,366.40	1,478.80	51.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,620.00	1,990.00	630.00	24.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,465.20</b>	<b>3,356.40</b>	<b>2,108.80</b>	<b>38.59</b>
<b>- Excess (S\$)</b>	<b>300.00</b>	<b>300.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>5,165.20</b>	<b>3,056.40</b>	<b>2,108.80</b>	<b>40.83</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>361.56</b>	<b>213.95</b>	<b>147.61</b>	<b>40.83</b>
<b>Nett Amount (S\$)</b>	<b>5,526.76</b>	<b>3,270.35</b>	<b>2,256.41</b>	<b>40.83</b>

### INSPECTION

Date of Assignment:	11/05/2021	
Date Inspected:	11/05/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*CARRIER ASSY-FRONT END MODULE	Not Necessary	675.00 FL	*- FL
3	1		*BEAM COMPLETE-FR BUMPER	Dented	497.00 FL	*497.00 FL
4	1		*COVER-FR BUMPER	Dented	633.00 FL	*633.00 FL
5	1		*GRILLE-FRONT BUMPER	Cut	262.00 FL	*262.00 FL
6	1		*GRILLE ASSY-RADIATOR	Cut	223.00 FL	*223.00 FL
7	1		*MOULDING-FRONT BUMPER, LH	Cut	36.00 FL	*36.00 FL
8	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	84.00 FL	*- FL
9	1		*COVER-DAYTIME RUNNING LIGHT, LH	Not Necessary	12.00 FL	*- FL
10	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
11	1		*LAMP ASSY-HEAD, LH	Not Necessary	1,040.00 FL	*- FL
					<b>Sub Total (\$\$)</b>	<b>3,544.00 1,703.00</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>698.80 336.60</b>
					<b>Total Parts (\$\$)</b>	<b>2,845.20 1,366.40</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE FRT BUMPER & AFFECTED AREAS	New	800.00	400.00
2	RESPRAY ON FRT BUMPER & AFFECTED AREAS	New	480.00	480.00
3	REMOVE & INSTALL RADIATOR & CONDENSER TO FACILITATE REPAIR	New	100.00	0.00
4	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	80.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	TO TOP UP A/C GAS AND CHECK A/C CONDITION	New	80.00	0.00
7	RESPRAY ON BONNET, RH FRONT FENDER (Supplementary)	New	960.00	960.00
<b>Gross Labour Cost (\$)</b>			<b>2,620.00</b>	<b>1,990.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >