

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21005743/T1QF3N2**Date:** 26/01/2022**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001432325		
Claimant Vehicle No :	SKA7035T	Insured Vehicle No :	SJH3282Y		
Date of Loss:	08/05/2021	Nature of Claim:	TP	Claim No:	257084

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA7035T	Engine No:	2AZH645790
Make & Model:	TOYOTA VELLFIRE, 2.4 Z (A)	Chassis No:	ANH208171825
Reg. Date:	25/03/2011 (Man. Year: 2011)	Odometer:	140880 km
Colour:	White		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50R18	Rear Tyre Size:	235/50R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,778.48	4,502.35	13,276.13	74.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,400.00	1,320.00	5,080.00	79.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	24,178.48	5,822.35	18,356.13	75.92
Approved Total (Overridden) (\$\$)		4,650.00		
(\$\$)	24,178.48	4,650.00	19,528.48	80.77
+ GST 7.00/7.00% (\$\$)	1,692.49	325.50	1,366.99	80.77
Nett Amount (\$\$)	25,870.97	4,975.50	20,895.47	80.77

INSPECTION

Date of Assignment:	11/05/2021	AP Automotive Services Pte Ltd
Date Inspected:	12/05/2021 Inspected At:	56 Loyang Way, #04-04 Loyang Enterprise Building
Estimated Period of Repair:	4.0 days	Singapore 508775

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jan 2022)
Parts:	M1-MPV	TOYOTA VELLFIRE 2.4 Z (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA7035T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	572.50 FL	*- FL
2	1		*BONNET CHROME	Not Necessary	462.85 FL	*- FL
3	1		*BONNET LOCK	Not Necessary	176.50 FL	*- FL
4	1		*HEAD LAMP LH & RH	N/s Cut/ O/s Not Necessary	4,500.00 FL	*2,085.00 FL
5	1		*HEAD LAMP GARNISH LH & RH	N/s Cut/ O/s Not Necessary	252.00 FL	*126.00 FL
6	1		*HEAD LAMP LOWER BRACKET LH & RH	N/s Cracked/ O/s Not Necessary	710.00 FL	*355.00 FL
7	1		*FRONT GRILLE ASSY	Not Necessary	1,020.00 FL	*- FL
8	1		*FRONT GRILLE LOGO-TOYOTA	Not Necessary	1,091.65 FL	*- FL
9	1		*FRONT FENDER LH	Bent	1,080.00 FL	*689.10 FL
10	1		*FRONT FENDER INNER PANEL LH (NPA)	Repair	0.00 FL	*- FL
11	1		*FRONT FENDER COWLING LH	Torn	180.00 FL	*180.00 FL
12	1		*FRONT BUMPER	Cracked	1,817.00 FL	*980.00 FL
13	1		*FRONT BUMPER FOGLAMP LH	Cracked	287.00 FL	*287.00 FL
14	1		*FRONT BUMPER FOGLAMP GARNISH LH	Cut	100.00 FL	*100.00 FL
15	2		*FRONT BUMPER SENSOR SET	Not Necessary	795.70 FL	*- FL
16	1		*FRONT BUMPER RETAINER LH	Cracked	67.70 FL	*67.70 FL
17	1		*FRONT BUMPER REINFORCEMENT BAR	Not Necessary	352.89 FL	*- FL
18	1		*FRONT BUMPER SPONGE	Not Necessary	90.45 FL	*- FL
19	1		*FRONT SUPPORT PANEL	Not Necessary	1,189.78 FL	*- FL
20	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	245.95 FL	*- FL
21	1		*FRONT ABSORBER LH	Not Necessary	430.00 FL	*- FL
22	1		*FRONT LOWER ARM LH	Not Necessary	815.00 FL	*- FL
23	1		*FRONT KNUCKLE LH	Not Necessary	625.00 FL	*- FL
24	1		*FRONT KNUCKLE BEARING LH	Not Necessary	576.00 FL	*- FL
25	1		*FRONT BEARING HUB LH (NPA)	Not Necessary	0.00 FL	*- FL
26	1		*FRONT DRIVE SHAFT LH (NPA)	Not Necessary	0.00 FL	*- FL
27	1		*FRONT TIE ROD END LH (NPA)	Not Necessary	0.00 FL	*- FL
28	1		*FRONT TIE ROD LH (NPA)	Not Necessary	0.00 FL	*- FL
29	1		*FRONT STABILIZER LINK LH (NPA)	Not Necessary	0.00 FL	*- FL
30	1		*HEADLAMP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
31	1		*FRONT GRILLE STICKER	Not Necessary	800.00 FS	*- FS
32	1		*FRONT LOGO STICKER	Not Necessary	150.00 FS	*- FS
33	1		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
34	1		*FRONT FENDER COWLING CLIPS	Necessary	200.00 FS	*20.00 FS
35	1		*FRONT SUPPORT TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
36	1		*FRONT RIM LH	Cut	2,500.00 FS	*800.00 FS
37	1		*FRONT TYRE LH	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **22,137.97** **5,719.80**
- List Item Discount on L Items 25.00/25.00% (\$\$) **4,359.49** **1,217.45**

Total Parts (\$\$) **17,778.48** **4,502.35**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,600.00	500.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,400.00	500.00
3	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	0.00
4	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	80.00
5	TO RNR UNDERCARRIAGE	New	250.00	150.00
6	TO CHECK WHEEL BALANCING	New	250.00	30.00
7	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
8	TO PERFORM RUST PROOFING	New	600.00	30.00
9	TO RNR FRONT SENSOR AND CHECK FUNCTION	New	600.00	0.00
10	TO CHECK WATER LEAK	New	150.00	0.00
11	TO CHECK WIRING AND HEADLAMP FOCUS }	New	150.00	30.00
12	TO CHECK WIRING AND FOG LAMP FUNCTION }	New	150.00	0.00
Gross Labour Cost (\$)			6,400.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >