

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21005746/AVCE2**Date:** 14/09/2021**REFERENCE**

Insured/Claimant:	NGUYEN THI THUY HANG	Policy No:	1900114968-01	
Date of Loss:	06/05/2021	Nature of Claim:	OD	Claim No: 6034613226SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML3588J		
Make & Model:	AUDI Q8, 3.0 TFSI QU TIP (A)	Engine No:	DCB067483
Reg. Date:	28/06/2019 (Man. Year: 2018)	Chassis No:	WAUZZZF11KD015567
Colour:	Blue	Odometer:	53205 km
Engine Capacity:	2995 cc		
Market Value/New Car Price:	S\$300,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/50 R20	Rear Tyre Size:	275/50 R20
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,255.00	8,216.56	17,038.44	67.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,112.00	3,352.00	5,760.00	63.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,367.00	11,568.56	22,798.44	66.34
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	32,967.00	10,168.56	22,798.44	69.16
+ GST 7.00/7.00% (S\$)	2,307.69	711.80	1,595.89	69.16
Nett Amount (S\$)	35,274.69	10,880.36	24,394.33	69.16

INSPECTION

Date of Assignment:	12/05/2021		
Date Inspected:	11/05/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR UPPER BUMPER	Deformed	1,362.00 FS	*1,089.60 FS
2	1		*REAR LOWER BUMPER	Deformed	2,669.00 FS	*2,135.20 FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
4	1		*REAR BUMPER TRIM - LEFT	Deformed	86.00 FS	*68.64 FS
5	1		*REAR BUMPER UPPER TRIM - CENTER	Not Necessary	129.00 FS	*- FS
6	1		*REAR BUMPER LOWER TRIM - CENTER	Cut	423.00 FS	*338.40 FS
7	1		*REAR BUMPER UPPER SPOILER	Deformed	815.00 FS	*651.60 FS
8	1		*REAR BUMPER CLOSING ELEMENT - LH	Damaged	95.00 FS	*75.84 FS
9	1		*REAR BUMPER CLOSING ELEMENT TRIM - LH	Cut	244.00 FS	*195.20 FS
10	1		*REAR BUMPER LOWER SPOILER	Not Necessary	575.00 FS	*- FS
11	1		*REAR BUMPER DIFFUSER	Not Necessary	1,261.00 FS	-
12	1		*REAR BOOT LID CONTROL UNIT	Not Necessary	411.00 FS	*- FS
13	1		*REAR BOOT LID ANTHENA AERIAL	Not Necessary	109.00 FS	*- FS
14	1		*REAR BOOT LID ANTHENA AERIAL RETAINER	Not Necessary	19.00 FS	*- FS
15	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,417.00 FS	*- FS
16	2		*REAR BUMPER SEAL - LH / RH	Not Necessary	28.00 FS	*- FS
17	1		*REAR BUMPER HOLDING STRAP	Not Necessary	182.00 FS	*- FS
18	1		*REAR BUMPER GUIDE SECTION - CENTER	Not Necessary	142.00 FS	*- FS
19	1		*REAR BUMPER GUIDE SECTION - LEFT	Not Necessary	67.00 FS	*- FS
20	1		*REAR PARKING AID SENSOR	Not Necessary	244.00 FS	*- FS
21	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
22	1		*REAR BUMPER LIGHT REFLECTOR - LH	Cracked	136.00 FS	*108.40 FS
23	1		*OUTER TAIL LIGHT - LH	Not Necessary	1,455.00 FS	*- FS
24	1		*OUTER TAIL LIGHT TRIM - LH	Not Necessary	44.00 FS	*- FS
25	1		*INNER TAIL LIGHT - CENTER	Cut	3,354.00 FS	*2,683.20 FS
26	1		*INNER TAIL LIGHT TRIM - LH	Not Necessary	44.00 FS	*- FS
27	1		*REAR BOOT LID TAILGATE TRIM	Not Necessary	484.00 FS	*- FS
28	1		*REAR BOOTLID	Repair	5,556.00 FS	*- FS
29	2		*REAR BOOT LID CLIP	Not Necessary	3.00 FS	*- FS
30	1		*REAR BOOT LID ADHESIVE	Not Necessary	19.00 FS	*- FS
31	1		*REAR FENDER PROTECTIVE FILM	Not Necessary	160.00 FS	*- FS
32	1		*REAR BOOT LID GASKET FLAP	Not Necessary	292.00 FS	*- FS
33	1		*REAR WINDOW	Not Necessary	1,174.00 FS	*- FS
34	1		*PRIMER	Not Necessary	20.00 FS	*- FS
35	2		*REAR BUMPER LONG SPOILER	Not Necessary	462.00 FS	*- FS
36	1		*AUDI EMBLEM	Necessary	138.00 FS	*110.00 FS
37	1		*Q8 EMBLEM	Necessary	99.00 FS	*79.04 FS
38	1		*QUATTRO EMBLEM	Necessary	99.00 FS	*79.04 FS
39	2		*REAR WHEEL ARCH COVER - LH / RH	Necessary	754.00 FS	*602.40 FS
40	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
41	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 25,255.00 8,216.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY	New	480.00	0.00
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID	New	480.00	0.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	New	400.00	0.00
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	New	200.00	0.00
6	TO RESPRAY REAR BUMPER, REAR LOWER BUMPER, REAR LID AND BOTH REAR WHEELARCH TRIMS	New	4,300.00	2,200.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,700.00	600.00
Gross Labour Cost (S\$)			9,112.00	3,352.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >