

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21005768/KTF3Q2
Date: 23/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900016493
Claimant Vehicle No :	SLN2572L	Insured Vehicle No :	GBJ2165T
Date of Loss:	09/05/2021	Nature of Claim:	TP
		Claim No:	5183492982SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN2572L		
Make & Model:	KIA CARENS, 1.7 (A)	Engine No:	D4FDGH118101
Reg. Date:	27/04/2017 (Man. Year: 2016)	Chassis No:	KNAHU815VH7172387
Colour:	Metallic Grey	Odometer:	158628 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	CST 9 mm	Rear Left Side:	Firenza 1 mm
Front Right Side:	CST 9 mm	Rear Right Side:	Firenza 1 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

6/23/2021

Adjuster Report

Date of Assignment: 12/05/2021

Date Inspected: 12/05/2021 Inspected At:

Lian Hong Seng Auto Trading (HQ)
BLK 5035 Ang Mo Kio, Industrial Park 2 #01-345
Singapore

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/23/2021

Adjuster Report

MARKET VALUE:\$66,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR	Dented	0.00 F	*- F
2	1		*FRT RH DOOR HINGE	Distorted	0.00 F	*- F
3	1		*FRT RH DOOR WING MIRROR	Repair	0.00 F	*- F
4	1		*FRT RH DOOR OUTER PILLAR	Repair	0.00 F	*- F
5	1		*FRT BUMPER	Cracked	0.00 F	*- F
6	1		*FRT BUMPER BRACKET	Broken	0.00 F	*- F
7	1		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
8	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
9	1		*FRT RH FENDER	Dented	0.00 F	*- F
10	1		*FRT RH FENDER INNER SHIELD	Distorted	0.00 F	*- F
11	1		*FRONT RH WHEEL BEARING	Distorted	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >