

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|--------------------------------------|-----------------|----------|-----------------------|--|
| | SOMPO INSURAN | CE SINGAPORE PL | F | Ref: | CS/SMO21005769/Uuf3n2 | |
| | 50 RAFFLES PLAC SINGAPORE LAND | CE #03-03 D TOWERSINGAPORE 048623 | [| Date: | 24/05/2021 | |
| | | | (| Code: | SMO | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SKS 165C | Veh. Inspected | | SLZ 7691E | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | CMTD2101477/LOR | Excess (\$) | | 0.00 | |
| | Assign From | GRACE TEO | Assign Date | | 12/05/2021 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | TOYOTA C-HR HYBRID (A) | c.c | | 1797 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2018 | |
| | Chassis No. | ZYX102116050 | Colour | | BLACK | |
| | Odometer | 221473 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. | 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 215/60 R17 | WEST LAKE | | 7 mm | |
| | L/H Front Tyre | 215/60 R17 | WEST LAKE | | 7 mm | |
| | R/H Rear Tyre | 215/60 R17 | WEST LAKE | | 7 mm | |
| | L/H Rear Tyre | 215/60 R17 | WEST LAKE | | 7 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 10/05/2021 | Inspection Date | ! | 17/05/2021 | |
| | Survey held at | BIK 8 KAKI BUKIT AVE 4, #06-31 | , PREMIER | | | |
| | Repairer | HUA HONG PTE LTD | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days | | | | | |