



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 6848B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	CRACKED	3,548.90	2,275.00
1	FRONT BUMPER SIDE PAD	DEFORMED	265.90	265.90
1	FRONT BUMPER LOWER REINFORCEMENT	BENT	2,856.30	2,150.00
2	FRONT BUMPER STEP METAL GARNISH LH @\$385.20	LOWER BENT	770.40	385.20
1	FRONT BUMPER SIDE RETAINER LH	NECESSARY	385.90	385.90
1	FRONT BUMPER SIDE LOWER METAL BRACKET LH	DENTED	365.20	365.20
1	FRONT HEADLAMP LH	CRACKED	1,589.60	1,042.00
1	FRONT HEADLAMP BRACKET LH	CRACKED	152.80	59.00
1	FRONT HEADLAMP GARNISH LH	NOT NECESSARY	165.90	-
1	FRONT WHEEL ARCH PANEL LH	CRACKED	2,436.20	2,085.00
1	FRONT WHEEL ARCH SIGNAL LAMP LH	NOT NECESSARY	128.30	-
	LESS 10% DISCOUNT		-	-901.32
			12,665.40	8,111.88
	<u>LABOUR</u>			
	PANEL BEATING, TO WELD, REALIGN DAMAGED PARTS.		2,000.00	600.00
	SPRAY PAINTING.	NOT NECESSARY	1,600.00	-
	CHECK WIRING ON HEADLAMP AND FOCUSING.		120.00	30.00
	ANTI RUST.	NOT NECESSARY	80.00	-
			3,800.00	630.00
	GRAND TOTAL		16,465.40	8,741.88
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,000.00

Report Ref No. CS/UOI21005771/Avf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.