

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Tel : 6844-1985 Fax : 6844-5185

Reg : 201838521G

Vehicle Number : XD6848B

Vehicle Model : MAN TGS 26.320 *Veron*

Accident Date : 30.04.2021

Original Reg Date : 08.03.2013

Date : 17.05.2021

Chassis : WMA26SZZ9CP038846

TP Ins. UOI

ESTIMATE

1	1 pc	Front Bumper <i>cracked</i>			3,548.90
2	1 pc	Front Bumper Side Pad <i>dented</i>			265.90
3	1 pc	Front Bumper lower reinforcement <i>Bent</i>		2150 X	2,856.30
4	2 pc	Front Bumper Step metal Garnish LH <i>Bent lower</i>	385.20	385.20	770.40
5	1 pc	Front Bumper side retainer Lh <i>new</i>			385.90
6	1 pc	Front Bumper side lower metal bracket LH <i>Dented</i>			365.20
7	1 pc	Front Headlamp LH <i>Cracked</i>		1042	1,589.60
8	1 pc	Front Headlamp bracket LH <i>cracked</i>		59	152.80
9	1 pc	Front Headlamp Garnish LH <i>new</i>		X	165.90
10	1 pc	Front Wheel arch panel LH <i>Cracked</i>		2085	2,436.20
11	1 pc	Front Wheel arch signal lamp LH <i>new</i>		X	128.30

12,665.40

9013.20

8111.88

Labour charge

Panel Beating , to weld , realign damaged parts		600	2,000.00
Spray painting		X	1,600.00
Check Wiring on headlamp and focussing		30	120.00
Anti Rust		X	80.00

total \$ 16,465.40

630

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Wheel: 874.88

H/S: 7K

05 Days.