

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21005775/ETF3E2

**Date:** 16/06/2021

### REFERENCE

Insured/Claimant: KHOO MEOW LONG Policy No: 2070133334  
Date of Loss: 11/05/2021 Nature of Claim: OD Claim No: 2634536910SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMV3383E**  
Make & Model: MITSUBISHI ECLIPSE CROSS, 1.5 CVT S/R (A) Engine No: 4B40HB2945  
Reg. Date: 15/10/2020 (Man. Year: 2019) Chassis No: JMAXTGK1WLZ000707  
Colour: Red Odometer: 14182 km  
Engine Capacity: 1499 cc  
Market Value/New Car Price: S\$113,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18  
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm  
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,569.36	3,026.08	2,543.28	45.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,370.00	3,740.00	1,630.00	30.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,939.36</b>	<b>6,766.08</b>	<b>4,173.28</b>	<b>38.15</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>765.76</b>	<b>473.63</b>	<b>292.13</b>	<b>38.15</b>
<b>Nett Amount (S\$)</b>	<b>11,705.12</b>	<b>7,239.71</b>	<b>4,465.41</b>	<b>38.15</b>

### INSPECTION

Date of Assignment: 12/05/2021

Date Inspected: 12/05/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

Estimated Period of Repair: 8.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*COVER, RR BUMPER, LH	Broken	117.00 FL	*117.00 FL
3	1		*COVER, RR BUMPER, RH	Not Necessary	117.00 FL	*- FL
4	1		*EXTENSION, RR BUMPER	Broken	152.00 FL	*152.00 FL
5	1		*FACE, RR BUMPER	Broken	556.00 FL	*556.00 FL
6	1		*REINFORCEMENT, RR BUMPER	Bent	497.00 FL	*497.00 FL
7	1		*BRKT, R/BMPR FACE SIDE, RH	Not Necessary	25.00 FL	*- FL
8	1		*BRKT, R/BMPR FACE SIDE, LH	Not Necessary	25.00 FL	*- FL
9	1		*BRACKET, RR BUMPER	Broken	16.00 FL	*16.00 FL
10	1		*PANEL, RR END	Not Necessary	475.00 FL	*- FL
11	1		*W/STRIP, TAILGATE OPENING	Not Necessary	194.00 FL	*- FL
12	1		*PANEL ASSY, TAILGATE	Dented	984.00 FL	*984.00 FL
13	1		*PIN, TAILGATE WINDOW	Necessary	5.00 FL	*5.00 FL
14	1		*DAM, TAILGATE, LWR	Necessary	13.00 FL	*13.00 FL
15	2		*CLIP, TAILGATE	Necessary	8.00 FL	*8.00 FL
16	1		*SPACER, TAILGATE	Necessary	8.00 FL	*8.00 FL
17	1		*SPACER, TAILGATE	Necessary	8.00 FL	*8.00 FL
18	4		*FASTENER, WINDSHIELD	Necessary	24.00 FL	*24.00 FL
19	1		*GLASS, TAILGATE WINDOW	Not Necessary	524.00 FL	*- FL
20	2		*SPACER, QTR WINDOW	Necessary	16.00 FL	*16.00 FL
21	1		*MARK, ECLIPSE CROSS	Necessary	87.00 FL	*87.00 FL
22	1		*MARK, THREE-DIA	Necessary	58.00 FL	*58.00 FL
23	1		*TRIM, RR END	Not Necessary	122.00 FL	*- FL
24	1		*MUFFLER, EXHAUST MAIN	Dented	600.00 FL	*600.00 FL
25	1		*HANGER, EXHAUST MUFFLER	Not Necessary	24.00 FL	*- FL
26	1		*GASKET, CATALYTIC CONVERTER	Necessary	11.00 FL	*11.00 FL
27	1		*HANGER, EXHAUST MUFFLER	Not Necessary	23.00 FL	*- FL
28	1		*PIPE, EXHAUST, CTR	Not Necessary	1,582.00 FL	*- FL
29	1		*LAMP ASSY, BACKUP, LH	Broken	118.00 FL	*118.00 FL
30	1		*MOULDING, RR WHEEL ARCH, LH	Not Necessary	153.00 FL	*- FL
31	1		*CLIP, RR BUMPER (6PCS) (Supplementary)	Necessary	36.00 FL	*36.00 FL
32	1		*BUZZER, KEYLESS OPERATION, RR (Supplementary)	Broken	91.00 FL	*91.00 FL
33	1		*RIVERT, FR BUMPER (3PCS) (Supplementary)	Necessary	15.00 FL	*15.00 FL
34	1		*CORE, RR BUMPER (Supplementary)	Broken	41.00 FL	*41.00 FL
35	1		*REAR BUMPER GARNISH (Supplementary)	Broken	443.00 FL	*443.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,218.00</b>	<b>3,924.00</b>
<b>- List Item Discount on L Items 23.00/23.00% (\$\$)</b>	1,648.64	897.92
<b>Total Parts (\$\$)</b>	<b>5,569.36</b>	<b>3,026.08</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE REAR BUMPER, END PANEL, BOOT & AFFECTED AREA	New	1,800.00	900.00
2	PAINT WORK ON REAR BUMPER, BOOT & END PANEL	New	1,050.00	700.00
3	REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR	New	120.00	80.00
4	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	160.00	0.00
5	REMOVE & INSTALL REAR UPP WINDSCREEN GLASS FOR FACILITATE REPAIR	New	240.00	240.00
6	REMOVE & INSTALL REAR LOWER WINDSCREEN GLASS FOR FACILITATE REPAI	New	240.00	180.00
7	TO APPLY UPP WINDSCREEN SEALANT	New	80.00	80.00
8	TO APPLY LOWER WINDSCREEN SEALANT	New	80.00	80.00
9	PERFORM RUST PREVENTION	New	80.00	40.00
10	TO APPLY SEALANT ON AFFECTED AREA	New	80.00	0.00
11	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
12	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
13	TO SUPPLY C & C EMBLEM	New	40.00	40.00
14	TO REPLACE REAR EXHAUST MUFFLER	New	450.00	450.00
15	REPAIR REAR END PANEL (Supplementary)	New	450.00	450.00
16	SPRAY PAINT REAR END PANEL (Supplementary)	New	350.00	350.00
			<b>Gross Labour Cost (\$\$)</b>	<b>5,370.00</b>
				<b>3,740.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >