



CYCLE & CARRIAGE

AIG - OD (REVERT)
SURVEY: 12/05/21
LKK - STEVE

VEHICLE NO : SMV 3383E

MODEL : MIT/ECLIPSE cross 1.5 T/C

WIP : 10953

Material	:	\$	<u>3,006.08</u>
Labour	:	\$	<u>3,760.00</u>
Sub-Total	:	\$	<u>6,766.08</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>6,766.08</u>
GST 7%	:	\$	<u>473.63</u>
Grand Total	:	\$	<u>7,239.71</u>
Finalise By/Date : <u>Army on 04/06/21</u>			

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 08 WORKING DAYS + 4 days (2 wk ends)

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 12/05/2021	Cust No/Name	KCV16145/KH00 MEOW LONG
	Reg No/Reg Date	SMV3383E*# / 15/10/2020
	Date In/Mileage	12/05/2021/ 14182
	Chassis/Package	JMAXTGK1WLZ000707 /T1P
	Engine No	4B40HB2945
	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C STYLE SR (T34)
	Colour/Trim	P62 RED DIAMOND / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	04/06/2021/ 12:43	TLK	884 / Lauro Songcuan	10953

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, BOOT & AFFECTED AREAS				900.00 ✓
E PNT98000 SPRAY PAINT ON REAR BUMPER & BOOT				700.00 ✓
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR				80.00 ✓
E PNT88000 REMOVE & INSTALL REAR UPPER WINDSCREEN GLASS FOR FACILITATE REPAIR				240.00 ✓
E PNT88000 REMOVE & INSTALL REAR LWR WINDSCREEN GLASS FOR FACILITATE REPAIR				180.00 ✓
M SUNDRY APPLY REAR UPPER WINDSCREEN SEALANT				80.00 ✓
M SUNDRY APPLY REAR LOWER WINDSCREEN SEALANT				80.00 ✓
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED PORTIONS				40.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
M SUNDRY SUPPLY C&C EMBLEM				40.00 ✓
A 15900099 REPLACE REAR EXHAUST MUFFLER				450.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
E PNT88000 REPAIR REAR END PANEL → <i>Supp</i>				450.00 X
E PNT98000 SPRAY PAINT REAR END PANEL → <i>Supp</i>				350.00 X
X COVER,RR BUMPER,LH ✓	1.00	117.00	23.00	90.09 ✓
X EXTENSION,RR BUMPER ✓	1.00	152.00	23.00	117.04 ✓

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 12/05/2021	Cust No/Name	KCV16145/KH00 MEOW LONG
	Reg No/Reg Date	SMV3383E*# / 15/10/2020
	Date In/Mileage	12/05/2021/ 14182
	Chassis/Package	JMAXTGK1WLZ000707 /T1P
	Engine No	4B40HB2945
	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C STYLE SR (T34)
	Colour/Trim	P62 RED DIAMOND / BK BLACK


Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	04/06/2021/ 12:43	TLK	884 / Lauro Songcuan	10953

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X FACE,RR BUMPER ✓	1.00	556.00	23.00	428.12 ✓
X PANEL ASSY,TAILGATE ✓	1.00	984.00	23.00	757.68 ✓
X PIN,TAILGATE WINDOW ✓	1.00	5.00	23.00	3.85 ✓
X DAM,TAILGATE,LWR ✓	1.00	13.00	23.00	10.01 ✓
X CLIP,TAILGATE ✓	2.00	4.00	23.00	6.16 ✓
X SPACER,TAILGATE ✓	1.00	8.00	23.00	6.16 ✓
X SPACER,TAILGATE ✓	1.00	8.00	23.00	6.16 ✓
X FASTENER,WINDSHIELD ✓	4.00	6.00	23.00	18.48 ✓
X SPACER,QTR WINDOW ✓	2.00	8.00	23.00	12.32 ✓
X MARK,ECLIPSE CROSS ✓	1.00	87.00	23.00	66.99 ✓
X MARK,THREE-DIA ✓	1.00	58.00	23.00	44.66 ✓
X MUFFLER,EXHAUST MAIN ✓	1.00	600.00	23.00	462.00 ✓
X GASKET,CATALYTIC CONVERTER ✓	1.00	11.00	23.00	8.47 ✓
X CLIP,RR BUMPER → Supp	6.00	6.00	23.00	27.72 X
X REINFORCEMENT,RR BUMPER ?	1.00	497.00	23.00	382.69 X
X BUZZER,KEYLESS OPERATIO,RR	1.00	91.00	23.00	70.07 X
X RIVET,FR BUMPER	3.00	5.00	23.00	11.55 X
X CORE,RR BUMPER	1.00	41.00	23.00	31.57 X
X LAMP ASSY,BACKUP,LH ?	1.00	118.00	23.00	90.86 ?
X REAR BUMPER GARNISH → Supp	1.00	443.00	23.00	341.11 X
X BRACKET,RR BUMPER ?	1.00	16.00	23.00	12.32 ?
Z TEXT				
AIG OD CLAIM - REVERT				
DOA: 11.05.2021				
SURVEY: STEVE (LKK)				
08 DAYS				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	3,006.08		Nett	6,766.08
Labour	3,500.00	7% GST on	6766.08	473.63
Standard Menu	0.00			
Specialist Job	0.00		Total Payable	7,239.71
Diagnostics Job	0.00			
Sundry/Others	260.00			
Total(w/o GST)	6,766.08			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMV 3383 E

<u>Materials</u>		<u>Cost \$</u>
1	Clip, RR Bumper (6 pcs)	36.00 ✓ nec
2	Buzzer, Keyless Operation, RR	91.00 ✓ BR
3	Rivet, FR Bumper (3 pcs)	15.00 ✓ nec
4	Core, RR Bumper	41.00 ✓ BR
5	Rear Bumper Garnish	443.00 ✓ BR
		<hr/>
		626.00
	23% Discount	143.98
		<hr/>
		482.02
 <u>Labour</u>		
1	Repair Rear End Panel	450.00 ✓
2	Spray Paint Rear End Panel	350.00 ✓
		<hr/>
		800.00
	Labour & Materials	1,282.02
	7% GST	89.74
	Total	<hr/>
		1,371.76

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens
Tel. # 6568 4658

CAR NO: SUV 3383E

WIP: 10955

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	?/SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Clip X6	?/SUPP		✓ MC	
2	Bracket RR Bumper	?/SUPP		✓ CUT	
3	Reinforcement RR Bumper	?/SUPP		✓ OT	
4	Rear Bumper Granish	?/SUPP		✓ RR	Steve
5	Buzzer, Keyless Operation, RR	?/SUPP		✓ RR	17/5/21
6	COTE ASSY L	?/SUPP		✓ RR (Chain)	
7	Lamp assy Backup LH	?/SUPP		✓ RR	
8	RIVETS X 4	?/SUPP		✓ MC	
9		?/SUPP			
10	Repair rear end Panel \$450	?/SUPP		✓	
11	Paint rear end Panel \$350	?/SUPP			
12		?/SUPP			
13		?/SUPP			
14		?/SUPP			
15		?/SUPP			
16		?/SUPP			
17		?/SUPP			
18		?/SUPP			
19		?/SUPP			
20		?/SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	17/5/21	Steve
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Eclipse Cross

SURVEYOR: Steve - blk

All DTCs

2021.05.21

Item	Setting	Information
M.U.T.-3 Version		SEW21031-00
V.C.I. Version		B179
Vehicle Information		GK1W 2020MY

SMV 3383 E.

→ Read DTC only. Before

All DTCS

2021.05.21

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
ACC/FCM	ACCSCFCM_4B080004	C2236 C2239 C2229	RR corner sensor signal lost LH back sensor signal lost Shift position abnormality	Stored Stored Stored
Multi Around Monitor	CAMERA_94080100	B2501	Rear view camera fault	Stored
EPB	EPB_4C080000		No DTCS	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		No DTCS	
BSW	BSW_RAD_MASTER_A 0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0 080000		Non-equipped System or Communication Error	
HUD	HUD_9E080000		No DTCS	

Item	Setting	Information
M.U.T.-3 Version		SEW21031-00
V.C.I. Version		B179
Vehicle Information		GK1W 2020MY

GMV 3383 E.

→ Read & clear DTC.

After

All DTCS

2021.05.21

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
ACC/FCM	ACCSCFCM_4B080004		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		No DTCS	
EPB	EPB_4C080000		No DTCS	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		No DTCS	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	
HUD	HUD_9E080000		No DTCS	