



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV16145/KHOO MEOW LONG
	Reg No/Reg Date	SMV3383E*# / 15/10/202
	Date In/Mileage	12/05/2021/ 0
	Chassis No	JMAXTGK1WLZ000707
	Engine No	4B40HB2945
	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C STYLE SR
	Colour/Trim	P62 RED DIAMOND / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	12/05/2021/ 12:27	QUK	282 / Kevin Leong	10953			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1800.00
REPLACE REAR BUMPER, END PANEL, BOOT & AFFECTED AREA								
E PNT98000								1050.00
PAINT WORK ON REAR BUMPER, BOOT & END PANEL								
E PNT88000								120.00
REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR								
E PNT88000								160.00
REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR								
E PNT88000								240.00
REMOVE & INSTALL REAR UPP WINDSCREEN GLASS FOR FACILITATE REPAIR								
E PNT88000								240.00
REMOVE & INSTALL REAR LOWER WINDSCREEN GLASS FOR FACILITATE REPAIR								
M SUNDRY								80.00
TO APPLY UPP WINDSCREEN SEALANT								
M SUNDRY								80.00
TO APPLY LOWER WINDSCREEN SEALANT								
M SUNDRY								80.00
PERFORM RUST PREVENTION								
M SUNDRY								80.00
TO APPLY SEALANT ON AFFECTED AREA								
A 54900099								30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								
M SUNDRY								40.00
TO SUPPLY C & C EMBLEM								
A 15900099								450.00
TO REPLACE REAR EXHAUST MUFFLER								
M SUNDRY								50.00
SUNDRIES								
M COVER,RR BUMPER,LH					1.00	117.00	23.00	90.09
M COVER,RR BUMPER,RH					1.00	117.00	23.00	90.09

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV16145/KHOO MEOW LONG
	Reg No/Reg Date	SMV3383E*# / 15/10/202
	Date In/Mileage	12/05/2021/ 0
	Chassis No	JMAXTGK1WLZ000707
	Engine No	4B40HB2945
	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C STYLE SR
	Colour/Trim	P62 RED DIAMOND / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	12/05/2021/ 12:27	QUK	282 / Kevin Leong	10953
Description of Goods / Services					
	Qty	Unit Price	Disc%	Amount	
M EXTENSION,RR BUMPER	1.00	152.00	23.00	117.04	
M FACE,RR BUMPER	1.00	556.00	23.00	428.12	
M REINFORCEMENT,RR BUMPER	1.00	497.00	23.00	382.69	
M BRKT,R/BMPR FACE SIDE,RH	1.00	25.00	23.00	19.25	
M BRKT,R/BMPR FACE SIDE,LH	1.00	25.00	23.00	19.25	
M BRACKET,RR BUMPER	1.00	16.00	23.00	12.32	
M PANEL,RR END	1.00	475.00	23.00	365.75	
M W/STRIP,TAILGATE OPENING	1.00	194.00	23.00	149.38	
M PANEL ASSY,TAILGATE	1.00	984.00	23.00	757.68	
M PIN,TAILGATE WINDOW	1.00	5.00	23.00	3.85	
M DAM,TAILGATE,LWR	1.00	13.00	23.00	10.01	
M CLIP,TAILGATE	2.00	4.00	23.00	6.16	
M SPACER,TAILGATE	1.00	8.00	23.00	6.16	
M SPACER,TAILGATE	1.00	8.00	23.00	6.16	
M FASTENER,WINDSHIELD	4.00	6.00	23.00	18.48	
M GLASS,TAILGATE WINDOW	1.00	524.00	23.00	403.48	
M SPACER,QTR WINDOW	2.00	8.00	23.00	12.32	
M MARK,ECLIPSE CROSS	1.00	87.00	23.00	66.99	
M MARK,THREE-DIA	1.00	58.00	23.00	44.66	
M TRIM,RR END	1.00	122.00	23.00	93.94	
M MUFFLER,EXHAUST MAIN	1.00	600.00	23.00	462.00	
M HANGER,EXHAUST MUFFLER	1.00	24.00	23.00	18.48	
M GASKET,CATALYTIC CONVERTER	1.00	11.00	23.00	8.47	
M HANGER,EXHAUST MUFFLER	1.00	23.00	23.00	17.71	
M PIPE,EXHAUST,CTR	1.00	1582.00	23.00	1218.14	
M LAMP ASSY,BACKUP,LH	1.00	118.00	23.00	90.86	
M MOULDING,RR WHEEL ARCH,LH	1.00	153.00	23.00	117.81	

Confirm &amp; accepted by

	<b>Nett</b>	<b>9,657.34</b>
7% GST on	<b>9657.34</b>	<b>676.01</b>
<b>Total Payable</b>		<b>10,333.35</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.