

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21005779/KPA3Q2
Date: 16/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SLF2539B	Insured Vehicle No :	SMR5642R
Date of Loss:	11/05/2021	Nature of Claim:	TP
		Claim No:	4319482619SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF2539B		
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Engine No:	L15B4037716
Reg. Date:	19/08/2016 (Man. Year: 2016)	Chassis No:	RU11117711
Colour:	Metallic Pearl White	Odometer:	89641 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,626.64	1,256.56	370.08	22.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	1,210.00	540.00	30.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,376.64	2,466.56	910.08	26.95
Approved Total (Overridden) (S\$)		1,950.00		

(S\$)	3,376.64	1,950.00	1,426.64	42.25
+ GST 7.00/7.00% (S\$)	236.36	136.50	99.86	42.25
Nett Amount (S\$)	3,613.00	2,086.50	1,526.50	42.25
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,333.95		
Global Sum Settlement (S\$)		2,330.00		

INSPECTION

Date of Assignment: 12/05/2021

Date Inspected: 12/05/2021

Inspected At:

Wei Lee Motor Works (HQ)
 BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32
 Singapore 575644

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Cut	508.80 FL	*508.80 FL
2	1		*REAR BUMPER SIDE	Bent	118.50 FL	*118.50 FL
3	1		*REAR FENDER	Bent	802.40 FL	*802.40 FL
4	1		*TAILLAMP	Serviceable	462.60 FL	*- FL
5	1		*ARCH GARNISH	Bent	96.00 FL	*96.00 FL
6	1		*GARNISH CLIP	Necessary	45.00 FL	*45.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	2,033.30	1,570.70
- List Item Discount on L Items 20.00/20.00% (\$)	406.66	314.14
Total Parts (\$)	1,626.64	1,256.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE/REINSTALL TRIANGLE GLASS	New	120.00	60.00
2	TO REMOVE /REINSTALL REAR SEATER ,INNER GARNISH ENABLE REPAIR JOB CARRY OUT TO REMOVE DAMAGED PARTS N ATTACHMENTS REPAIR /RESHAPE DENTED AREAS	New	180.00	100.00
3	TO REPLACE /ALIGN ALL PARTS INTO POSITION	New	850.00	600.00
4	TO SPRAY PAINT	New	600.00	450.00
Gross Labour Cost (S\$)			1,750.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >