

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21005780/AQF3N2
Date: 24/06/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210017783
Claimant Vehicle No : SME7296L **Insured Vehicle No :** SKV113L
 Date of Loss: 10/05/2021 Nature of Claim: TP Claim No: 5827143253SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME7296L**
 Make & Model: BMW 528i, 2.0 L (A) Engine No: A3440057N20B20A
 Reg. Date: 21/12/2011 (Man. Year: 2011) Chassis No: WBAXG32000C593475
 Colour: Blue Odometer: 63909 km
 Engine Capacity: 1997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40R19 Rear Tyre Size: 245/40R19
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,419.00	3,425.40	993.60	22.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	480.00	470.00	49.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,369.00	3,905.40	1,463.60	27.26
Approved Total (Overridden) (S\$)		3,100.00		
Nett Amount (S\$)	5,369.00	3,100.00	2,269.00	42.26
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 12/05/2021
 Date Inspected: 20/05/2021 Inspected At: Ysk Auto Workshop (HQ)
 No.1 Kaki Bukit Avenue 6, #01-49 Autobay
 Singapore 417883
 Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,546.00 F	*1,546.00 FL
2	1		*FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
3	1		*FRONT BUMPER SIDE HOLDER	Not Necessary	78.00 F	*- FL
4	1		*FRONT BUMPER FOG LAMP	Not Necessary	285.00 F	*- FL
5	1		*FRONT BUMPER SENSOR	Not Necessary	250.00 F	*- FL
6	1		*HEADLAMP RH	Cut	2,210.00 F	*2,210.00 FL
					Sub Total (\$)	4,419.00 3,806.00
					- List Item Discount on L Items 0.00/10.00% (\$)	0.00 380.60
					Total Parts (\$)	4,419.00 3,425.40

F=Franchise part. L=ListItemDisc.

LKK Auto Consultants Pte Ltd/SME7296L/24/06/2021 10:29

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	200.00
2	SPRAY PAINTING	New	400.00	200.00
3	WIRING	New	50.00	30.00
4	TO REMOVE FRONT BUMPER SENSOR	New	100.00	50.00
Gross Labour Cost (\$\$)			950.00	480.00

LKK Auto Consultants Pte Ltd/SME7296L/24/06/2021 10:29

< END OF ESTIMATES >