

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Reg No : 199405410K	ESTIMATE	Longac	GST Reg No : MR-850011		
Invoice Name & Address	Owner Name & Vehicle Info				
Tan Guangfan (chen Guangfan) BLK 259C PUNGGOL FIELD #15-57	Cust No/Name Reg No/Reg Date Date In/Mileage Chassis No	SLR1636Y KNAFJ411MJ5	N GUANGFAN (CHEN GUANGFAN) / 02/08/201 0 725374		
SINGAPORE 823259	Engine No	No G4FGGH636446			
Contact No Mobile: 94301482	Make/Model Colour/Trim	KIA/FORTE K MST METAL S	3 1.6 A L 189 TREAM / WK SATURN BLACK		

Account No	Terms	Date/Time Printed CSE	Operato	1	established to the second	WIP No		1000 T 1 T 1 T 1 T 1 T 1 T 1 T 1 T 1 T 1	
CSM00081	Cash	12/05/2021/ 10:33	442 / C			33271			
CC-100001	Casn	Description of Goods / Serv		en von 1 per 2 met 1.	Qty	Unit Price	Disc%	Ar	nount
E PNT88000		Description of Goods / Serv			ů.			1280	2750.00
	R BUMPER	, BOOTLID, REAR END PANEL	640 x 2						1500.00
F PNTOROGO			THE DANIEL	tea 10				1100	
SPRAY PAI	NT FOR R	EAR BUMPER, BOOTLID, REAR	END PANEL	sso x 2				fo	100.00
E PNT88000	INSTALL	PARKING SENSOR					100	4	300.00
E PNT88000	INSTALL	ARRING SENSOR					120	•	300.00
REMOVE &	INSTALL I	REAR COMPARTMENT TRIMS							50.00
M SUNDRY		WITH FRAME - (M)							
		WZ111 110012			п _			40	80.00
M SUNDRY APPLY SEAL	ANT FOR	ACCIDENT PORTION	ממחל	J 90'	(a) 5i				40.00
4 SUNDRY				10	1110				
C&C LUGU									30.00
90000001	NC . ELE	CTRICAL SYSTEM					ď.		280.00
10028001									280.00
TO CARRY O	UT DIAGNO	STIC CHECK USING HI-SCAN	PRO TEST						
USING HI-SO	CAN PRO 1	TEST							20.00
SUNDRY						*		/	
Sundry COVER-RR BL	IMDED /	00			1.00	688.00			688.00 315.00
COVER-RR BU	MPER.CTR	CUT			1.00	315.00 318.00	00.00	/	318.00
BEAM-RR BUM		BR 1 X MM			1.00 1.00	3.00	00.00		3.00
BRACKET-RR	BEAM UPR	MIG, KH a - 1 KIM			1.00	3.00	00.00		3.00
BRACKET-RR		MTG X AIM			1.00	120.00	00.00	_	120.00
STAY-RR BUM		1 / 101			1.00	120.00	00.00		120.00
STAY-RR BUM	PER LH	THE MIC PH P X NM			1.00	29.00	00.00		29.00
BRACKET-RR	BUMPER S	TOE PHONE OF CIGA			1.00	29.00	00.00		29.00
BRACKET-RR	BUMPER S	J KIKI			1.00	5.00	00.00		5.00
BRACKET-RR	BEAM LWR	PILO A S CHA			1.00	5.00	00.00		5.00
BRACKET-RR	BEAM LWR,	VIII.			1.00	1365.00	00.00		1365.00
PANEL ASSY-1	TRUNK LIC	· · · · · · · · · · · · · · · · · · ·	- 62 - 62	(44)			1		

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has commenced. after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

FSTIMATE

GST Reg No : MR-8500111-X

MOTION	EQ LIMA LE	G51 Keg NO : MK-0500111
Invoice Name & Address		Owner Name & Vehicle Info
Tan Guangfan (chen Guangfan)	Cust No/Name Reg No/Reg Date	
BLK 259C PUNGGOL FIELD #15-57 SINGAPORE 823259	Name of the Control o	KNAFJ411MJ5725374 G4FGGH636446
Contact No Mobile: 94301482	Make/Model	KIA/FORTE K3 1.6 A L 189 MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	Statistics and a series of the	WIP No		
CSM00081				442 / CocoL	u	33271		
31100081	Cash	12/05/2021/ 10:33 Description of Goods			Qty	Unit Price		Amount
A DANGE AG	DACK		37 001 11000		1.00	324.00	00.00	324.0 112.0
M PANEL ASS		LID X NIN			1.00	112.00	00.00	100.0
M LATCH ASS	SY-IKUNK	OPNG X KM			1.00	100.00	00.00	58.0
	IKUNK LIL	CRY	(1:1)		1.00	242.00	00.00	242.0
M TRIM-TRAM M LAMP ASSY	ADEVD U	MB INSIDE, RH	R CRodlid)		1.00	368.00	00.00	368.0
M LAMP ASSI	-REAR CO	MOTNATION DH Y IVI	M		1.00	242.00	00.00	242.0
M LAMP ASSI	-REAR CO	MB INSIDE, LH	UK		1.00 1.00	18.00	00.00	18.0
M LAMP ASS	-LICENSE	PLATE LH X MV			1.00	18.00	00.00	18.0
M LAMP ASSY	-LICENSE	PLATE, RH A NIV			1.00	37.00		37.0
M LOGO ASSY	-KIA SUB	- IPC			1 00	35.00	00.00	35.0
M EMBLEM-CE	RATO	/ M []	一九品		0156			
			\sim 1711	$ \alpha \alpha $	atte			
			\mathcal{D}	11 11 11 (31140	7		
					WIL AL			
			Stone	(LKK)	MIC IC	-3		
			0101		010			
			17/5	11 17.30	am III		- 1	
			ן טין יו	1 , 1,0	<i>γ</i> '	01		
						be - SL	1	
						. 0-	J	
					6 Ash	dasc		
					6 M	.,47	,	
						V		
		LKK Auto Consultants	ence notify	1		*		
		the Repairer of the follo	wing:	i				
		 To resurvey before/after spi To display damaged part(s) 	during resurvey					
		Parts prices are subject to compared to compare the compared to compared to compare the compared to compared to compare the compared to compared	onfirmation					
		Third party survey is on a "\"	Vithout Preiudice" ba	sis				
		No illegal modification(s) is	allowed					
		- Cuestamontany itam/s) mus	the resurveyed and	ı				
8		is subject to final approval fi	om Insurance Comp	any		, il		
Confirm & ac	cented by	Autor Jodged by Bonsises		l		A.		
COULTIN G CC		•				Net		9,704.0 679.2
		Signature: Date:			7% GST on	9704.0	D	0/9.2
		COR.			_	4 - 1 - N L 1 -		10,383.2
				400	То	tal Payable	8	10,303.2

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen. the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

INSURANCE CO.: LONPAC

Supplementary Parts For Registration No.: SLR 1636 Y

	<u>Materials</u>		Cost (\$)
1 2	Clips (x10) Emblem K3		20.00 / nec 15.00 / nec
2	Linbletti (()	T-4 184-1-2-1-	
		Total Materials	35.00

	<u>Labour</u>		<u>Cost (\$)</u>		
1 2	Repair rear end panel Respray rear end panel		200.00 /		
		Total Labour	550.00		
		Taxable amount	585.00		
		7% GST	40.95		
		Grand total	\$ 625 <u>.95</u>		

Thank You.

Yours faithfully

LOI AI TING

SENIOR OFFICER - ADMIN KIA SERVICE CENTRE DID : 6568 4556 / 6568 4501

DID: 6568 4556 / 6568 4501 FAX: 6565 1240 / 6567 5258