

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21005788/T1RS3Q2
Date: 27/10/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100503757
Claimant Vehicle No :	SHB610J	Insured Vehicle No :	SLB481S
Date of Loss:	08/05/2021	Nature of Claim:	TP
		Claim No:	9462137542SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB610J	Engine No:	2ZR1411851
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKN36U305749710
Reg. Date:	17/09/2014 (Man. Year: 2014)	Odometer:	617028 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195/85 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,075.95	204.69	8,871.26	97.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,752.00	840.00	1,912.00	69.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,827.95	1,044.69	10,783.26	91.17
Approved Total (Overridden) (S\$)		1,000.00		

Nett Amount (S\$)	11,827.95	1,000.00	10,827.95	91.55
	<hr/>			
+ Car Rental (4.0 x S\$133.75/day) (S\$)		535.00		
+ Doc/Search Fee (S\$)		7.00		
	<hr/>			
Nett Liability (S\$)		1,542.00		
	<hr/>			

INSPECTION

Date of Assignment: 11/05/2021

Date Inspected: 11/05/2021

Estimated Period of Repair: 3.0 days

Inspected At:

SMRT Taxis Pte Ltd (HQ)
60 WOODLANDS INDUSTRIAL PARK E4
Singapore 757705

Adjuster: ACCUSER4

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
2	1		*FENDER LINER FRT/RH (DISC 25%)	Deformed	171.70 F	*128.78 F
3	1		*FENDER LINER PAD ,FR WHEEL RH (DISC 25%)	Necessary	49.30 F	*36.98 F
4	1		*BUMPER CLIPS	Not Necessary	1.61 F	*- F
5	1		*BUMPER SUPPORT F/RH	Not Necessary	76.40 F	*- F
6	1		*BUMPER ENERGY ABSORBER FRT	Not Necessary	78.80 F	*- F
7	1		*BUMPER REINFORCEMENT FRT	Not Necessary	498.40 F	*- F
8	1		*ARM SUB-ASSY ,FR BUMPER LH	Not Necessary	250.40 F	*- F
9	1		*ARM SUB-ASSY ,FR BUMPER RH	Not Necessary	250.40 F	*- F
10	1		*BUMPER GRILLE SUB-ASSY ,LOWER	Not Necessary	311.10 F	*- F
11	1		*FOG LAMP RH	Not Necessary	295.20 F	*- F
12	1		*GRILLE ,RADIATOR LOWER NO.2	Not Necessary	94.60 F	*- F
13	1		*BUMPER LIP FRT	Not Necessary	139.60 F	*- F
14	1		*BUMPER FRT ABSORBER LOWER	Not Necessary	127.70 F	*- F
15	1		*UNDER COVER CENTER	Not Necessary	448.30 F	*- F
16	1		*TYRE	Not Necessary	126.74 F	*- F
17	1		*PILLAR ,FR BODY	Not Necessary	363.10 F	*- F
18	1		*WHEEL HUB FRT	Not Necessary	549.70 F	*- F
19	1		*MIRROR ASSY ,RH	Not Necessary	1,307.10 F	*- F
20	1		*MIRROR LAMP RH	Not Necessary	65.30 F	*- F
21	1		*COVER ,OUTER MIRROR ,RH	Not Necessary	107.40 F	*- F
22	1		*HEAD LAMP RH	Not Necessary	945.20 F	*- F
23	1		*FENDER FRT/RH	Repair	723.40 F	*- F
24	1		*WHEEL DISC ,FRONT	Repair	1,484.20 F	*- F
25	1		*BUMPER FRT	Repair	482.00 F	*- F
26	1		*BUMPER SUPPORT F/LH	Not Necessary	76.40 F	*- F

F=Franchise part.

Total Parts (S\$) 9,075.95 204.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	676.00	300.00
2	SPRAY PAINT	New	1,476.00	500.00
3	TO REMOVE AND REFIX WING MIRROR	New	120.00	0.00
4	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	40.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
6	TO REPLACE SUNDRY PARTS	New	100.00	0.00
7	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
8	TO WASH AND VACUUM	New	60.00	0.00
			Gross Labour Cost (S\$)	2,752.00
				840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >