

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21005789/ERS3Q2**Date:** 17/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900085565
Claimant Vehicle No :	SHC4470P	Insured Vehicle No :	SML1238H
Date of Loss:	11/05/2021	Nature of Claim:	TP
		Claim No:	9178000392SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4470P		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS098763
Reg. Date:	12/10/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU603573062
Colour:	Beige	Odometer:	0 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,494.94	552.00	7,942.94	93.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,250.00	1,270.00	1,980.00	60.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,744.94	1,822.00	9,922.94	84.49
Approved Total (Overridden) (S\$)		1,700.00		
Nett Amount (S\$)	11,744.94	1,700.00	10,044.94	85.53
+ Loss of Use (5.0 x S\$83.83/day) (S\$)		419.15		
+ Car Rental (5.0 x S\$108.61/day) (S\$)		543.05		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		2,669.20		
Global Sum Settlement (S\$)		2,600.00		

INSPECTION

Date of Assignment:	12/05/2021	
Date Inspected:	12/05/2021	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MOULDING ASSY ,BODY ROCKER PANEL ,RH (DISC 25%)	Broken	576.00 F	*432.00 F
2	1		*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F
3	1		*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F
4	2		*PAD ,RR BUMPER ,RH & LH 1	Not Necessary	3.80 F	*- F
5	2		*PAD ,RR BUMPER ,RH & LH 2	Not Necessary	3.80 F	*- F
6	2		*PAD ,RR BUMPER ,RH & LH 3	Not Necessary	3.80 F	*- F
7	2		*SEAL ,RR BUMPER ARM ,RH & LH	Not Necessary	11.00 F	*- F
8	1		*PAD ,RR BUMPER ,CTR	Not Necessary	2.20 F	*- F
9	1		*GUARD ,RR BUMPER LOWER	Not Necessary	558.30 F	*- F
10	1		*RETAINER ,RR BUMPER ,RH	Not Necessary	112.70 F	*- F
11	1		*SEAL ,RR BUMPER RH	Not Necessary	85.20 F	*- F
12	1		*CLIPS PIECE FRT & RR BUMPER	Not Necessary	1.50 F	*- F
13	1		*FILLER ,RR BUMPER RH	Not Necessary	119.90 F	*- F
14	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
15	1		*COVER ,REAR FLOOR UNDER ,RH	Not Necessary	169.50 F	*- F
16	1		*COVER ,REAR FLOOR UNDER CENTER	Not Necessary	222.60 F	*- F
17	1		*HINGE ASSY ,REAR DOOR ,UPPER RH	Not Necessary	83.30 F	*- F
18	1		*HINGE ASSY ,REAR DOOR ,LOWER RH	Not Necessary	73.30 F	*- F
19	1		*DOOR REAR MOTOR ASSY ,POWER WINDOW	Not Necessary	768.60 F	*- F
20	1		*DOOR REAR WINDOW REGULATOR SUB-ASSY ,RH	Not Necessary	200.70 F	*- F
21	1		*DOOR OUTER HANDLE REAR RH	Not Necessary	93.90 F	*- F
22	1		*WIRE REAR DOOR RH	Not Necessary	206.70 F	*- F
23	1		*PATCH ,SIDE PANEL REAR END ,RH & LH	Not Necessary	33.70 F	*- F
24	1		*LINER ,REAR FENDER ,RH	Not Necessary	135.80 F	*- F
25	2		*HUB & BEARING ASSY ,RH & LH	Not Necessary	554.20 F	*- F
26	1		*TYRE	Not Necessary	126.74 F	*- F
27	1		*PANEL SUB-ASSY ,REAR DOOR RH	Repair	1,243.90 F	*- F
28	1		*PANEL SUB-ASSY ,FENDER REAR RH	Repair	824.80 F	*- F
29	1		*WHEEL DISC	Repair	1,555.10 F	*- F
30	1		*COVER ,RR BUMPER ASSY	Repair	423.90 F	*- F

F=Franchise part.

Total Parts (\$\$) **8,494.94** **552.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	676.00	400.00
2	SPRAY PAINT	New	1,854.00	780.00
3	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	60.00
4	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	0.00
5	TO TRANSFER DOOR MECHANISM	New	120.00	0.00
6	TO REPLACE SUNDRY PARTS	New	100.00	10.00
7	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
8	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
9	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$)			3,250.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >