

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



| NTUC INCOME INSURANCE CO-OPERATIVE LTD | | | Ref: | NS/INC21005790/Etf3e2 | |
|--|---|-------------------------|---------|-----------------------|--------------------|
| 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 | | | Date: | 02-06-2021 INC4 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SLK 9010L | _ | nspected | SMB 1334R |
| | Policy No. | | Cover | age (\$) | 0.00 |
| | Claim No. | MT/1131436-002 | Exces | s (\$) | 0.00 |
| | Assign From | | Assign | n Date | 12/05/2021 |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | MAN NL320F | c.c | | 10518 |
| | Engine No. | HIDDEN | Year o | f Reg. | 2013 |
| | Chassis No. | WMAA22ZZ8D7001778 | Colou | r | MULTI COLOUR |
| | Odometer | 857862 | Steeri | ng | IN ORDER |
| | Brakes | IN ORDER | Modifi | cation | STANDARD ALLOY RIM |
| | General | FAIR | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance |
| | R/H Front Tyre | 275/70 R22.5 | GOOD' | | 5 mm |
| | L/H Front Tyre | 275/70 R22.5 | GOOD, | YEAR | 5 mm |
| | R/H Rear Tyre | 275/70 R22.5 (D) | GOOD, | | 5/5 mm |
| | L/H Rear Tyre | 275/70 R22.5 (D) | GOOD' | | 5/5 mm |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 10/05/2021 | Inspec | tion Date | 12/05/2021 |
| | Survey held at | SMRT AUTOMOTIVE SERVICE | S PTE L | TD | |
| | 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 | | | | |
| 5a. Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days | | | | |