

[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	2014 BMW 420 I (SMY4982D)
Date of Loss	11 May 2021
Time of Loss	6:30
Loss Description	SMY4982D (INSD) DAMAGED DUE TO SMOKE
Comment	

Workshop Details

Total Rebate Amount	0
Nett Loss Amount	\$36,471.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	20



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SMY4982D

Registration State

SINGAPORE

Mileage

109203

Purchase Date

DD/MM/YYYY



Registration Date *

30/09/2015



Age of Vehicle

5

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATION

Manufacturing
Year

2014

2014

Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION


Driver Name

HARRISON DORILYN
CIERVO

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	BMW	B.M.W.
Model	420 I	420I M SPOR
Type		
Type of Paint		
Chassis No	WBA3V12020PX80718	WBA3V12020
Engine No	A9000906N20B20B	A9000906N2
Engine Capacity		1997
Sum Insured	0	0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth	7 November 1974	DD/MM/YY
Age	46	
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	19	
Driver License #		
License Type		
License Issue Date		DD/MM/YY

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value	0	<input type="text" value="100000"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YY"/> 
Address	299 BEDOK SOUTH AVE 3, #01-06, 469298, Singapore	<input type="text"/>
Address type	Residential	<input type="text" value="▼"/>
Gender	Female	<input type="text" value="▼"/>
Marital status	Married	<input type="text" value="▼"/>
Identification #	S7483380B	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

14/05/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

225/40R19

Front left side

PIRELLI8mm

Front right side

PIRELLI8mm

Spare wheel

Rear Tyre Size

255/35R19

Rear left side

PIRELLI5mm

Rear right side

PIRELLI5mm



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

0

Salvage%

0

Discount%

0

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Cash Loss

Yes

No

Paint Material Ratio

80

Part Supplied by AXA

Yes

No

Save



<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour







Miscellaneous

Summary

Parts

Add		Approve		Deny		Submit All								
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)

Labour

Add		Approve		Deny		Submit All				
EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS	0	180	0	0	Reviewing		
	0		TO REMOVE DOOR'S FITTINGS	0	60	0	0	Reviewing		
	0		TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	0	400	0	0	Reviewing		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNT

ADJUSTED
AMOUNT

COMMENT

REMOVE



0

(REPAIR COST
NOT
CONCLUDE)
(EXCLUDE
CHECK ITEMS
S\$1934.50
NETT)

Reviewing

0

0



0









DAYS OF
REPAIR : 4 DAYS









Reviewing







0







0














EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	N/S FRONT DOOR (COST PLUS 10%) (WCP)	Deny	0	0	SERVICEABLE	
	0	N/S FRONT DOOR LOWER SEAL BIG (COST PLUS 10%) (WCP)	Reviewing	0	132	BURNT	
	0	N/S FRONT DOOR LOWER SEAL SMALL (COST PLUS 10%) (WCP)	Reviewing	0	44	BURNT	
	0	N/S FRONT DOOR OUTER WEATHERSTRIP (COST PLUS 10%) (WCP)	Deny	0	0	SERVICEABLE	









EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	N/S FRONT DOOR OUTER MIRROR TRIANGLE SEAL (COST PLUS 10%) (WCP)	Reviewing	0	19.8	BURNT	
	0	N/S FRONT DOOR OUTER MOULDING (COST PLUS 10%) (WCP)	Deny	0	0	SERVICEABLE	
	0	N/S FRONT DOOR A PILLAR SEAL (COST PLUS 10%) (WCP)	Reviewing	0	88	BURNT	
	0	N/S FRONT DOOR MIRROR BASE OUTSIDE SEAL (COST PLUS 10%) (WCP) (\$143.00)	Reviewing	0	0	* CHECK	









EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	N/S FRONT DOOR CORNER MOULDING (COST PLUS 10%) (WCP) (\$44.00)	Reviewing	0	0	* CHECK	
	0	N/S FRONT DOOR INNER VERTICAL SEAL (COST PLUS 10%) (WCP) (\$60.50)	Reviewing	0	0	* CHECK	
	0	N/S FRONT DOOR INNER SOUND INSULATION - TOP (COST PLUS 10%) (WCP) (\$110.00)	Reviewing	0	0	* CHECK	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	N/S FRONT DOOR INNER SOUND INSULATION - LOWER (COST PLUS 10%) (WCP) (\$110.00)	Reviewing	0	0	* CHECK	
	0	N/S FRONT DOOR INNER PULL HANDLE (COST PLUS 10%) (WCP)	Reviewing	0	143	BURNT	
	0	N/S FRONT DOOR INNER HANDLE ACCENT MOULDING (COST PLUS 10%) (WCP) (\$192.50)	Reviewing	0	0	* CHECK	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	N/S FRONT DOOR ARM REST IN LEATHER (COST PLUS 10%) (WCP)	Reviewing	0	385	BURNT	
	0	N/S FRONT DOOR INNER PULL HANDLE ALUMINIUM COVER (COST PLUS 10%) (WCP) (\$291.50)	Reviewing	0	0	* CHECK	
	0	N/S FRONT DOOR INNER PULL HANDLE BASE SUPPORT (COST PLUS 10%) (WCP)	Reviewing	0	137.5	BURNT	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	N/S FRONT DOOR WIREHARNESS (COST PLUS 10%) (WCP)	Reviewing	0	302.5	BURNT	
	0	N/S FRONT DOOR GLASS (COST PLUS 10%) (WCP) (\$319.00)	Reviewing	0	0	* CHECK	
	0	N/S FRONT DOOR TWITTER SPEAKER (COST PLUS 10%) (WCP)	Reviewing	0	203.5	BURNT	
	0	N/S FRONT DOOR REGULATOR (COST PLUS 10%) (WCP)	Deny	0	0	SERVICEABLE	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	N/S FRONT DOOR REGULATOR MOTOR (COST PLUS 10%) (WCP)	Deny	0	0	SERVICEABLE	
	0	N/S FRONT DOOR SENSOR (COST PLUS 10%) (WCP) (\$148.50)	Reviewing	0	0	* CHECK	
	0	N/S FRONT DOOR SPEAKER (MAIN) (COST PLUS 10%) (WCP)	Reviewing	0	264	BURNT	
	0	N/S FRONT DOOR LOCK CABLE (COST PLUS 10%) (WCP) (\$66.00)	Reviewing	0	0	* CHECK	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	N/S FRONT DOOR POWER WINDOW SWITCH PANEL (COST PLUS 10%) (WCP) (\$88.00)	Reviewing	0	0	* CHECK	
	0	N/S FRONT DOOR INNER TRIM BOARD (COST PLUS 10%) (WCP)	Reviewing	0	1760	BURNT	
	0	N/S FRONT DOOR LED MODULE FOR ARMREST (COST PLUS 10%) (WCP)	Reviewing	0	60.5	BURNT	
	0	N/S FRONT DOOR LED MODULE (COST PLUS 10%) (WCP) (\$49.50)	Reviewing	0	0	* CHECK	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	N/S FRONT DOOR OPTICAL CONDUCTOR UPPER LEFT (COST PLUS 10%) (WCP) (\$66.00)	Reviewing	0	0	* CHECK	
	0	N/S FRONT DOOR INNER HANDLE LIGHTING (COST PLUS 10%) (WCP) (\$66.00)	Reviewing	0	0	* CHECK	
	0	N/S FRONT DOOR GLASS SOLAR FILM (SN) (\$180.00)	Reviewing	0	0	* CHECK	



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$4,179.80
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Labour	\$0.00	\$640.00
Miscellaneous	\$0.00	\$3,539.80

Submit for Review