Postal Address: BLK 146, POTONG PASIR AVE I, #02-145 SINGAPORE 350146 Reg. No. 200005790R TEL NO: 62860155 (3 LINES) FAX: 62841539

SURVEY/ADJUSTING DAMAGES ON MOTOR VEHICLE, LICENSED APPRAISERS.

AUTOMOBILE INSPECTION REPORT

TO: MS POO SOO CHIN

PAGE : 1

C/o HS AUTOMOTIVES PTE LTD

DATE

: 26/04/2021

2 KAKI BUKIT AVE 2 #02-25 AUTOHUB

OUR REF

: TPA/0005/21

SINGAPORE 417921

REFERENCE & PARTICULARS:

THIRD PARTY CLAIM

VEHICLE NO : SJM5327M INSPECTION REQUEST BY : THE OWNER

INSURED OWNER

: AS ABOVE

ASSIGNMENT DATE

: 31/03/2021

POLICY NO

: N.A

SUM INSURED

: NOT APPLICABLE

CLAIM NO

: N.A

ACCIDENT DATE

: 29/03/2021

EXCESS AMOUNT

: NOT APPLICABLE

PARTICULARS OF DAMAGED VEHICLE:

MAKE/MODEL

: HONDA FIT 1.3 (A)

PRE-ACCIDENT CONDITION: GOOD

YEAR

: 07/01/2009(COE TILL

: IN ORDER STEERING

31/12/2023)

CAPACITY

: 1339

BRAKES

: IN ORDER

ENGINE NO

: NOT VISIBLE

MILEAGE

: 181299

CHASSIS NO.

: GE61094260

COLOUR

: RED

TYRE CONDITION:

SIZE (FRONT): 185/60R15

\$IZE(REAR): 185/60R15 OFF SIDE

FRONT REMAINING THREADS:

NEAR SIDE

5 MM YOKOHAMA

5 MM YOKOHAMA

REAR REMAINING THREADS :

5 MM YOKOHAMA

5 MM YOKOHAMA

GENERAL DESCRIPTION OF DAMAGE:

DAMAGE TO THE REAR PORTION. FOR FURTHER DETAILS, PLEASE REFER TO OVERLEAF.

INSPECTION:

SURVEY HELD AT

: HS AUTOMOTIVE PTE LTD

2 KAKI BUKIT AVE 2 #02-25 AUTOHUB@KAKI BUKIT, SINGAPORE 417921

PHOTOGRAPH

: 101

INSPECTED DATE

: 31/03/2021

REMARKS

(SUBJECT TO POLICY CONDITION)

WE HAVE REINSPECTED THE ABOVE VEHICLE AND FOUND THAT IT IS IN ORDER THIS SURVEY WAS CONDUCTED STRICTLY "WITHOUT PREJUDICE"

ESTIMATED NORMAL PERIOD OF REPAIRS: ( 8 ) WORKING DAYS

IN ACCORDANCE WITH YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. This estimate covers visible damages only. Should there be any discrepancy or unseen items in this survey, kindly notify the company within (7) days from the date hereof. Otherwise this estimate/acceptance shall be treated as valid .







VEHICLE NO : SJM5327M

POLICY NO : N.A

CLAIM NO : N.A

*t* :

OUR REF : TPA/0005/21

## ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS:

S/N	YTQ	DESCRIPTIONS	COMMENTS/CONDITION	ORIGINAĻ QUOTATION	REVISED QUOTATION
		Material Items			,
1	1	REAR TAILGATE	DENTED	704 50	704 50 /
2	1	REAR TAILGATE EMBLEM "FIT"	NECESSARY	794.50 35.00	794.50
3	1	REAR TAILGATE OUTER GARNISH /		199.50	35.00 / 199.50 /
4	1	REAR TAILGATE OUTER GARNISH	NECESSARY	85.00	85,0078.
5	2	LOGO / REAR TAILGATE NUMBER PLATE LAM LH & RH /	P TORN	71.60	71.60
6	1	REAR TAILGATE THIRD BRAKE LAMP	X TORN SALL	100 00	100/00/
7	1	REAR TAILGATE WIPER ARM	DENTED	180.00 84.60	189.00
8	1	REAR TAILGATE WIPER BLADE	SERVICEABLE		84.60
9	1	REAR TAILGATE WIPER MOTOR	DENTED/BENT	45.00 238.70	0.00
10	1	REAR TAILGATE LOCK MECHANISM		189.50	238.70
11	1	REAR TAILGATE LOCK STRIKER	SERVICEABLE	28.00	189.50
12	1	REAR TAILGATE INNER TRIM BOARD		138.20	0.00
13	1	REAR TAILGATE INNER TRIM BOARD		58.40	138.20
•		HANDLE /	DENTED	38.40	58.40
14	1	REAR TAILGATE WINDSCREEN GLASS	/SHATTERED	800.00	800.00 /
15	1	REAR TAILGATE WINDSCREEN RUBBE	r necessary	58.00	58.00 /
16	1	REAR TAILGATE WEATHERSTRIP /	DEFORMED	145.80	145.80
17	2	REAR TAILGATE DAMPER LH & RH X	DENTED/BENT SVC	272.40	272,40 X
18	2	REAR TAILGATE HINGE LH & RH	SERVICEABLE	90.00	0.00
19	2	REAR TAILLAMP LH & RH 🖊	HOLDER TORN	512.40	512.40 /
20	1	REAR BUMPER /	DENTED/TORN	494.50	494.50 /
21	2	REAR BUMPER SIDE RETAINER LH &	BENT	57.00	57,00×
22	1	REAR END PANEL	DENTED	288.80	288.80 /
23	1	REAR END PANEL TOP GARNISH	DENTED/TORN	65.50	65.50 /
24	2	REAR END PANEL SIDE BRACKET LH & RH	SERVICEABLE	171.60	0.00
25	2	REAR FENDER INNER TRIM BOARD LE & RH - 1PC LH	H DENTED/TORN	576.00	288.00
26	1	ROOF LINING X SVC	DENTED/TORN	708.00	708,00 ×
		/ 10	4501.1	6,388.00	5,765.40
		SubTotal: Org 0.0% Rev -20.0% D	iscount	6,388.00	-1,153.08
			D	6,388.00	4,612.32
				0.00	0.00
		Total Material		\$6,388.00	\$4,612.32
		Special Nett Items			
1	1SET	REAR TAILGATE TOP SPOILER CLIP	NOT NECESSARY	28.00	0.00

VEHICLE NO : SJM5327M

POLICY NO : N.A

CLAIM NO

: N.A

OUR REF : TPA/0005/21

## ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS:

	QTY	DESCRIPTIONS	COMMENTS/CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
	1SET	REAR TAILGATE OUTER GARNISH .	NECESSARY	28.00	15.00
	1	REAR TAILGATE REVERSE CAMERA X	SHORTED WC	450.00	350.00
	1	REAR TAILGATE NUMBER PLATE	DENTED	50.00	45.00
	1SET	REAR TAILGATE INNER TRIM BOARD	NECESSARY	38.00	20.00
	1	REAR TAILGATE INNER CAMERA "IROAD V9" /	DENTED/SHORTED	380.00	380.00
	1	REAR TAILGATE WINDSCREEN SEALANT /	NECESSARY	100.00	40.00
	lSET	REAR BUMPER CLIP /	NECESSARY	38.00	30.00
_	1	REAR BUMPER REVERSE SENSOR /	SHORTED/MALFUNCTION	350.00	200.00
0	1SET	REAR END PANEL TOP GARNISH CLI	PNECESSARY	28.00	15.00
11	2SET	REAR FENDER INNER TRIM BOARD CLIP LH & RH - 1SET LH	NECESSARY	56.00	20.00
		,		1,546.00	1,115.00
				0.00	0.00
				1,546.00	1,115.00
				0.00	0.00
		Total S/Nett		\$1,546.00	\$1,115.00
		Labour & Misc			
		PANEL BEAT & REPLACE PARTS		880.00	650,00
		RESPRAY, PUTTY & POLISH AFFECTED PORTION		1,350.00	800.00
		CHECK & RECTIFY WIRING SYSTEM		80.00	30.00
4		REMOVE & TRANSFER TAILGATE COMPONENT		150.00	60.00
5		REMOVE & REFIT REAR WINDSCREEN	ı	150.00	120.00
6		INTERIOR UPHOLSTERY		180.00	80.00
7		REMOVE & INSTALL IN CAR CAMERA	A.	80.00	30.00
8		REMOVE & INSTALL REVERSE SENSO	DR	120.00	30.00
		VACUUM/CLEANING SERVICE		180.00	20.00
)		V.1.0001., C221.			

VEHICLE NO

: SJM5327M

POLICY NO

: N.A

CLAIM NO

: N.A

OUR REF

: TPA/0005/21

#### ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS:

s/N	QTY	DESCRIPTIONS	COMMENTS/CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
				0.00	0.00
				3,170.00	1,820.00
				0.00	0.00
		Total Labour		\$3,170.00	\$1,820.00
		Total Parts		\$7,934.00	\$5,727.32
		Total Parts And Labour		\$11,104.00	\$7,547.32
		CONTRACT JOB AS AGREED AT	LUMP SUM		\$6,000.00
				-	\$6,000.00

Nett Total

\$6,000.00

AUTOMOBILE INSPECTION SERVICES PTE LTD

Mr E. C. Looi MIMI AMSOE AMIRTE | Mr I. H. Looi BBM

| MIMI AIIRSM

AMSAE MSAAA Dip. MTM Licensed Appraiser

6130.88 20%: P900 5 Day