

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005798/URA3Q2
Date: 13/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700052363
Claimant Vehicle No :	SHC2531K	Insured Vehicle No :	SGP8889H
Date of Loss:	11/05/2021	Nature of Claim:	TP
		Claim No:	5520201580SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2531K	Engine No:	2ZR2F64044
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU603089747
Reg. Date:	05/12/2019 (Man. Year: 2019)	Odometer:	146229 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,356.50	477.22	879.28	64.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	1,280.00	600.00	31.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,236.50	1,757.22	1,479.28	45.71
+ GST 7.00/7.00% (S\$)	226.56	123.01	103.55	45.71

Nett Amount (S\$)	3,463.06	1,880.23	1,582.83	45.71
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$130.54/day) (S\$)		652.70		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,784.93		

INSPECTION

Date of Assignment: 14/05/2021

Date Inspected: 14/05/2021

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER	Repair	836.70 FL	*- FL
2	1		*REAR FENDER SHIELD RH	Not Necessary	134.20 FL	*- FL
3	1		*REAR RH WHEEL CAP	Cut	177.70 FL	*177.70 FL
4	1		*REAR BUMPER COVER	Deformed / Cut	458.60 FL	*458.60 FL
5	1		*REAR BUMPER SIDE BRACKET RH	Serviceable	94.80 FL	*- FL
6	1		*REAR DOOR COMFORT APP LOGO	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (\$)	1,782.00	636.30
- List Item Discount on L Items 25.00/25.00% (\$)		425.50	159.08
	Total Parts (\$)	1,356.50	477.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,050.00	700.00
2	SRPAY PAINTING CHARGE	New	600.00	500.00
3	REMOVE AND REFIX UPHOLSTERY	New	90.00	60.00
4	CHECK WIRING	New	60.00	20.00
5	TUFF COAT	New	80.00	0.00
Gross Labour Cost (S\$)			1,880.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >