



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 5469U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BODY PANEL-RH	BENT	2,585.50	1,308.00
1	REAR BUMPER SIDE RETAINER-LH	SERVICEABLE	64.50	-
1	REAR BUMPER SIDE RETAINER-RH	SERVICEABLE	64.50	-
	LESS 25% DISCOUNT		-	-327.00
			2,714.50	981.00
	<u>SPECIAL NETT ITEMS</u>			
1	BODY STICKER-RH (SN)	NECESSARY	400.00	180.00
1	WHEEL RIM HUB CAP-RH (SN)	DENTED	180.00	180.00
			580.00	360.00
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY.		1,600.00	700.00
	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		1,600.00	300.00
	TO APPLY RUST-PROOFING ON REPAIRED,REPLACED PANEL.		120.00	30.00
	TO REMOVE/REFIT PASSENGER SEAT TO FACILITATE REPAIRS.		200.00	120.00
	TO CHECK WIRING FUNCTIONS.		50.00	15.00
	WHEEL ALIGNMENT.		120.00	60.00
			3,690.00	1,225.00
	GRAND TOTAL		6,984.50	2,566.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,050.00

Report Ref No. CS/LPC21005799/Kvf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.