



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC21005799/Kvf3n2 Date: 08/07/2021 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBC 5253P	Veh. Inspected	GBA 5469U
	Policy No.		Coverage (\$)	0.00
	Claim No.	21/21/21/VC00/024541	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	14/05/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA HIACE (A)	c.c	2494
	Engine No.	HIDDEN	Year of Reg.	2005
	Chassis No.	JTFHS02P800020821	Colour	SILVER
	Odometer	431768 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195 R15X8	ARIVO	9 mm
	L/H Front Tyre	195 R15X8	ARIVO	9 mm
	R/H Rear Tyre	195 R15X8	ARIVO	9 mm
	L/H Rear Tyre	195 R15X8	ARIVO	9 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	05/05/2021	Inspection Date	14/05/2021
	Survey held at	YEE AUTO PTE LTD 160 SIN MING DRIVE #02-17 SIN MING AUTOCITY SINGAPORE 575722		
<b>5a. Remarks</b>				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	