

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21005801/EVF3E2

Date: 16/06/2021

REFERENCE

Insured/Claimant:	POOH SAY HUI PETER	Policy No:	2100361312		
Date of Loss:	12/05/2021	Nature of Claim:	OD	Claim No:	7754400779SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFG5959T	Engine No:	G4KJDH737117
Make & Model:	KIA SORENTO, 2.2 (A)	Chassis No:	KNAKU816ME5470783
Reg. Date:	09/01/2014 (Man. Year: 2013)	Odometer:	183550 km
Colour:	Brown		
Engine Capacity:	2359 cc		
Market Value/New Car Price:	S\$55,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,702.80	2,672.80	30.00	1.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	1,130.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,832.80	3,802.80	30.00	0.78
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	3,232.80	3,202.80	30.00	0.93
+ GST 7.00/7.00% (S\$)	226.30	224.20	2.10	0.93
Nett Amount (S\$)	3,459.10	3,427.00	32.10	0.93

INSPECTION

Date of Assignment:	14/05/2021	
Date Inspected:	17/05/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*COVER-FR BUMPER UPR	Crushed	817.00 FL	*817.00 FL
3	1		*COVER-FR BUMPER, LWR	Cut	735.00 FL	*735.00 FL
4	1		*GUARD ASSY-FRONT WHEEL, LH	Cut	92.00 FL	*92.00 FL
5	1		*GARNISH ASSY-FNDR SIDE, LH	Cut	116.00 FL	*116.00 FL
6	1		*WHEEL ASSY-ALUMINIUM	Cut	1,556.00 FL	*1,556.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,366.00	3,336.00
- List Item Discount on L Items 20.00/20.00% (\$)	663.20	663.20
Total Parts (\$)	2,702.80	2,672.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER & AFFECTED AREAS	New	400.00	400.00
2	SPRAY ON FRT BUMPER	New	350.00	350.00
3	TO REMOVE AND INSTALL FRT PARKING SENSOR	New	80.00	80.00
4	TO TRANSFER FRT LH RIM INCLUDING BALANCING	New	30.00	30.00
5	CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
Gross Labour Cost (\$\$)			1,130.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >