



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 8423Y

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|-------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | FRONT EMBOSS NUMBER PLATE (SN) | SERVICEABLE | 83.00 | - |
| 1 | SUNDRIES (SN) | NECESSARY | 80.00 | 80.00 |
| 1 | FRT BUMPER TOP CARRIER (SN) | SERVICEABLE | 387.60 | - |
| 1 | FRT BUMPER PANEL PRIMED (LINES PDC/ (SN) | DEFORMED | 901.75 | 901.75 |
| 1 | RH FOG LAMP SUPPORT (SN) | SERVICEABLE | 71.90 | - |
| 1 | RH GRID LATERAL (LUXURY / SPORT) (SN) | SCRATCHED | 111.40 | 111.40 |
| 1 | RH SIDE TRIM GRILLE (LUXURY) (SN) | SCRATCHED | 95.55 | 95.55 |
| 1 | SUPPORT NUMBER PLATE ECE (SN) | SERVICEABLE | 71.00 | - |
| 1 | RH FOG LAMP COVER (SN) | SERVICEABLE | 41.15 | - |
| 1 | GRATE CENTER (SN) | SERVICEABLE | 143.25 | - |
| 1 | FRT BUMPER PROTECTIVE STRIP CENTRE (SN) | CRACKED | 62.20 | 62.20 |
| 1 | FRT RH MOULDING (LUXURY) (SN) | SCRATCHED | 127.25 | 127.25 |
| 1 | FRT SHOCK ABSORBER (SN) | SERVICEABLE | 49.50 | - |
| 1 | FRONT GRILLE (LUXURY) (SN) | CRACKED | 699.40 | 699.40 |
| 1 | AIR DUCT TOP (SN) | SERVICEABLE | 100.85 | - |
| 1 | PLAQUE 82MM (SN) | NECESSARY | 71.95 | 71.95 |
| 1 | WASHER FLUID RESERVOIR (SN) | DEFORMED | 134.75 | 134.75 |
| 1 | GRATE CENTRE CLOSED (SPORT) (SN) (ADDITIONAL) | CRACKED | 143.25 | 143.25 |
| 1 | AIR DUCT FRAME (SN) (ADDITIONAL) | CRACKED | 186.55 | 186.55 |
| | | | 3,562.30 | 2,614.05 |
| | <u>LABOUR</u> | | | |
| | TO REPLACE FRONT BUMPER, CARRIER, AIR DUCT AND ATTACHMENTS. | | 3,400.00 | 2,550.00 |
| | TO PAINTING FRONT BUMPER. | | 1,038.00 | 986.00 |
| | TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS. | | 177.00 | 168.00 |
| | TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION. | | 177.00 | 168.00 |
| | | | 4,792.00 | 3,872.00 |
| | GRAND TOTAL | | 8,354.30 | 6,486.05 |

Report Ref No. CS/UOI21005803/R1tf3e2



| | | | |
|-----------------------------|--|--|----------|
| RECOMMENDED COST OF REPAIRS | | | 6,486.05 |
|-----------------------------|--|--|----------|

Report Ref No. CS/UOI21005803/R1tf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.