

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005805/URA3Q2
Date: 25/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100299012-09
Claimant Vehicle No :	SHA3991U	Insured Vehicle No :	SKF932Z
Date of Loss:	12/05/2021	Nature of Claim:	TP
		Claim No:	3546780452SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA3991U	Engine No:	G4LEKU411490
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU190702
Reg. Date:	08/04/2020 (Man. Year: 2019)	Odometer:	95588 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,602.60	4,555.28	2,047.32	31.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	1,700.00	450.00	20.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,752.60	6,255.28	2,497.32	28.53
+ GST 7.00/7.00% (S\$)	612.68	437.87	174.81	28.53

Nett Amount (S\$)	9,365.28	6,693.15	2,672.13	28.53
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$125.19/day) (S\$)		625.95		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,571.10		

INSPECTION

Date of Assignment: 14/05/2021

Date Inspected: 14/05/2021

Estimated Period of Repair: 4.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CENTRE MOULDING	Broken	451.25 FL	*451.25 FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
4	2		*REAR BUMPER STAY LH/RH	Not Necessary	276.20 FL	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
6	1		*BOOTLID COVER	Badly Dented	2,480.40 FL	*2,480.40 FL
7	1		*BOOTLID H EMBLEM	Necessary	38.00 FL	*38.00 FL
8	1		*BOOTLID EMBLEM IONID	Necessary	31.80 FL	*31.80 FL
9	1		*BOOTLID EMBLEM HYBRID	Necessary	24.30 FL	*24.30 FL
10	1		*BOOTLID LAMP RH	Not Necessary	870.40 FL	*- FL
11	1		*BOOTLID TAILLAMP RH	Not Necessary	794.40 FL	*- FL
12	1		*REAR REFLECTOR RH	Cracked	41.45 FL	*41.45 FL
13	1		*REAR BUMPER TOW COVER	Not Necessary	98.80 FL	*- FL
14	1		*RADAR BLIND SPOT RH	Shorted	1,625.00 FL	*1,625.00 FL
15	2		*REAR BUMPER BRACKET RH	Not Necessary	55.80 FL	*- FL
16	1		*REAR BUMPER PROTECTOR	Bent	50.00 FS	*50.00 FS
17	1		*REAR NUMBER PLATE W/HOLDER	Serviceable	55.00 FS	*- FS
18	1		*REAR REVERSE SENSOR	Cracked	180.00 FS	*180.00 FS
19	1		*REAR BUMPER SIDE UNDER CO	Cracked	108.00 FL	*108.00 FL
20	1		*APP LOGO REAR BONNET CTPL	Necessary	40.00 FS	*40.00 FS
21	1		*REAR BOOT LOGO CTPL	Necessary	30.00 FS	*30.00 FS
22	1		*REAR BOOT TEL NUMBER CTPL	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,157.00	5,611.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,554.40	1,056.32
Total Parts (\$\$)	6,602.60	4,555.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	900.00	700.00
2	SPRAY PAINTING CHARGE	New	800.00	750.00
3	REMOVE/REFIX REAR UPHOLSTERY	New	90.00	60.00
4	DIAGNOSE AND RESET ERROR CODE	New	240.00	120.00
5	TUFF KOTE	New	60.00	30.00
6	REMOVE/REFIX REVERSE SENSOR	New	60.00	40.00
Gross Labour Cost (\$\$)			2,150.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >