

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21005806/T1PA3Q2
Date: 12/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800071909-03
Claimant Vehicle No :	SHF39M	Insured Vehicle No :	SMA77U
Date of Loss:	08/05/2021	Nature of Claim:	TP
		Claim No:	2922925584SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHF39M		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2F45361
Reg. Date:	26/12/2019 (Man. Year: 2019)	Chassis No:	JTDKB3FU703089434
Colour:	Maroon	Odometer:	93195 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,558.30	869.03	9,689.27	91.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,001.00	430.00	2,571.00	85.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	13,559.30	1,299.03	12,260.27	90.42
	+ Loss of Use (2.5 x S\$50.00/day) (S\$)	125.00		
	+ Car Rental (2.5 x S\$112.35/day) (S\$)	280.88		

+ Doc/Search Fee (S\$)	7.00
Nett Liability (S\$)	1,711.91
Global Sum Settlement (S\$)	1,700.00

INSPECTION

Date of Assignment: 11/05/2021

Date Inspected: 11/05/2021

Estimated Period of Repair: 2.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,RR BUMPER ASSY (DISC 25%)	Deformed	485.60 F	*364.20 F
2	2		*PAD ,RR BUMPER ,RH & LH ,1 (DISC 25%)	Necessary	8.00 F	*6.00 F
3	2		*PAD ,RR BUMPER ,RH & LH ,2 (DISC 25%)	Necessary	8.00 F	*6.00 F
4	2		*PAD ,RR BUMPER ,RH & LH ,3(DISC 25%)	Necessary	22.00 F	*16.50 F
5	1		*SEAL ,RR BUMPER ARM ,RH & LH (DISC 25%) (2 PCS)	Necessary	22.60 F	*16.95 F
6	1		*CLIPS PIECE FRT & RR BUMPER (DISC 25%) (10 PCS)	Necessary	45.00 F	*33.75 F
7	1		*GUARD ,RR BUMPER LOWER (DISC 25%)	Deformed	374.50 F	*280.88 F
8	1		*PAD ,RR BUMPER ,CTR (DISC 25%) (3 PCS)	Necessary	33.00 F	*24.75 F
9	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
10	1		*RETAINER ,RR BUMPER ,LH	Not Necessary	132.60 F	*- F
11	1		*RETAINER ,RR BUMPER ,RH	Not Necessary	132.60 F	*- F
12	1		*COVER ,GUARD RR BUMPER LOWER	Not Necessary	22.00 F	*- F
13	1		*REAR BUMPER REFLECTOR ASSY ,REFLEX RH	Not Necessary	39.00 F	*- F
14	1		*REAR BUMPER REFLECTOR ASSY ,REFLEX LH	Not Necessary	39.00 F	*- F
15	1		*REAR BUMPER REINFORCEMENT	Not Necessary	332.70 F	*- F
16	1		*COVER ,REAR FLOOR UNDER ,RH	Not Necessary	175.10 F	*- F
17	1		*COVER ,REAR FLOOR UNDER CENTER	Not Necessary	229.90 F	*- F
18	1		*COVER ,REAR FLOOR UNDER ,LH	Not Necessary	241.90 F	*- F
19	1		*ANTENNA ,ELECTRICAL KEY	Not Necessary	72.00 F	*- F
20	1		*REVERSE SENSOR ,REAR BUMPER	Not Necessary	180.00 F	*- F
21	1		*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB	Not Necessary	913.60 F	*- F
22	1		*EMBLEM SUB-ASSY REAR	Not Necessary	47.90 F	*- F
23	1		*NAME PLATE (HYBRID) LUGGAGE COMPARTMENT	Not Necessary	54.60 F	*- F
24	1		*NAME PLATE (PRIUS) LUGGAGE COMPARTMENT	Not Necessary	54.60 F	*- F
25	1		*SMRT LOGO	Not Necessary	7.80 F	*- F
26	1		*STICKER DECAL 6555 8888	Not Necessary	21.60 F	*- F
27	1		*TAIL GATE PANEL SUB-ASSY ,BACK DOOR	Not Necessary	1,147.80 F	*- F
28	1		*TAIL GATE BACK DOOR HINGE ASSY ,LH	Not Necessary	61.00 F	*- F
29	1		*TAIL GATE BACK DOOR HINGE ASSY ,RH	Not Necessary	61.00 F	*- F
30	1		*TAIL GATE LOCK ASSY BACK DOOR	Not Necessary	467.00 F	*- F
31	1		*TAIL GATE LOCK COVER ,BACK DOOR	Not Necessary	30.20 F	*- F
32	1		*AUTO TAILGATE SYSTEM	Not Necessary	2,520.00 F	*- F
33	1		*SPOILER SUB-ASSY ,REAR	Not Necessary	1,575.40 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
34	1		*LAMP SET ,STOP CENTER	Not Necessary	192.30 F	* - F
35	1		*END PANEL SUB-ASSY ,BODY LOWER BACK	Not Necessary	651.00 F	* - F
36	1		*SEALANT SIKAFLEX	Not Necessary	37.00 F	* - F
F=Franchise part.						
					Total Parts (\$\$)	10,558.30
						869.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	845.00	200.00
2	SPRAY PAINT	New	1,476.00	200.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
4	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	30.00
5	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	0.00
6	TO REMOVE AND REFIX WIRE HARDESS	New	200.00	0.00
7	TO REPLACE SUNDRY PARTS	New	100.00	0.00
8	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			3,001.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >