

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21005807/T1PA3Q2
Date: 20/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SMB69M	Insured Vehicle No :	SW1819C
Date of Loss:	09/05/2021	Nature of Claim:	TP
		Claim No:	3903745393SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB69M		
Make & Model:	MERCEDES-BENZ OC500LE1830H, 12.0 D (A)	Engine No:	45795400124373
Reg. Date:	30/06/2009 (Man. Year: 2009)	Chassis No:	WEB63442021000178
Colour:	Green	Odometer:	769615 km
Engine Capacity:	11967 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8/8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,218.30	1,771.02	1,447.28	44.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,362.00	1,492.00	870.00	36.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,580.30	3,263.02	2,317.28	41.53
Approved Total (Overridden) (S\$)		2,900.00		

Nett Amount (S\$)	5,580.30	2,900.00	2,680.30	48.03
+ Loss of Use (3.5 x S\$250.00/day) (S\$)		875.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		3,782.00		
Global Sum Settlement (S\$)		3,780.00		

INSPECTION

Date of Assignment: 11/05/2021

Date Inspected: 11/05/2021

Estimated Period of Repair: 3.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WINDSCREEN FRT:L/H ,FOR MB OC500 BUS	Cracked	931.50 F	*931.50 FL
2	1		*COVER ,HEADLAMP :LH,FOR MB OC500 BUS	Cracked	621.00 F	*621.00 FL
3	1		*LAMP ,BLINKER:FRONT LEFT ,FOR MB OC 500 LE	Cracked	155.30 F	*155.30 FL
4	1		*HEADLAMP FOR MERCEDES OC500 LE,LEFT	Not Necessary	1,276.50 F	*- FL
5	1		*PRIMER (SIKA 206 G+P)	Necessary	80.00 FS	*80.00 FS
6	2		*ADHESIVE :DIRECT GLAZING	Necessary	74.00 FS	*74.00 FS
7	1		*ACTIVATOR	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,218.30	1,941.80
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	170.78
Total Parts (\$)	3,218.30	1,771.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,590.00	1,060.00
2	TO PUTTY & RESPRAY	New	772.00	432.00
Gross Labour Cost (S\$)			2,362.00	1,492.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >