



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 1185K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	WINDSCREEN	CRACKED	160.00	160.00
1	WINDSCREEN BRACKET	BENT / CUT	90.00	90.00
1	LHS MIRROR	BROKEN	58.00	58.00
1	RHS MIRROR	CUT	58.00	58.00
1	BRAKE LEVER	SCRATCHED	48.00	48.00
1	BALANCER RHS	CRACKED	25.00	25.00
1	HANDLE BAR	BENT	85.00	85.00
1	RHS FRONT SIGNAL LAMP	SCRATCHED	95.00	95.00
1	LHS FRONT SIGNAL LAMP	BROKEN	95.00	95.00
1	TOP COWLING	CRACKED	160.00	160.00
1	FRONT FENDER	CRACKED	140.00	140.00
1	FRONT RIM	BENT / CUT	680.00	680.00
1	SET FORK	TO REPAIR SEE LABOUR	980.00	-
1	STEERING STEM	SERVICEABLE	450.00	-
1	RHS FRONT PANEL	CRACKED	140.00	140.00
1	BRAKE PEDAL	TO REPAIR SEE LABOUR	85.00	-
1	FRONT EXHAUST PIPE COVER (CRACKED)	NOT CONSISTENT WITH THE IMPACT	65.00	-
1	REAR EXHAUST PIPE COVER (CRACKED)	NOT CONSISTENT WITH THE IMPACT	95.00	-
1	CLUTCH LEVER	CUT	48.00	48.00
1	BALANCER LHS	SCRATCHED	25.00	25.00
1	LHS FRONT PANEL	CUT	140.00	140.00
1	LHS FRONT CENTER PANEL	CRACKED	190.00	190.00
1	SIDE STAND	CUT	35.00	35.00
1	GEAR PEDAL	BENT	68.00	68.00
1	GEAR PEDAL ROD	BENT	30.00	30.00
1	LHS FRONT FOOTREST	BROKEN	65.00	65.00
1	LHS FRONT FOOTREST BRACKET	CRACKED	95.00	95.00
1	LHS REAR FOOTREST	CUT	65.00	65.00

Report Ref No. CS/SMO21005810/Uqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LHS REAR FOOTREST BRACKET	TO REPAIR SEE LABOUR	95.00	-
1	MAINSTAND	NOT NECESSARY	68.00	-
1	SWING ARM	NOT NECESSARY	580.00	-
1	REAR WHEEL SHAFT	CUT	68.00	68.00
1	REAR MUDGUARD	SERVICEABLE	85.00	-
1	BRAKE DISC	BENT	98.00	98.00
1	WHEEL SHAFT	BENT	58.00	58.00
1	FRONT NO. PLATE STICKER	NECESSARY	8.00	8.00
	LESS 10% DISCOUNT		-533.00	-282.70
			4,797.00	2,544.30
	<u>SPECIAL NETT ITEMS</u>			
1	STEERING CONE (SN)	NOT NECESSARY	120.00	-
1	LHS CARRIER BOX (SN)	CUT	480.00	400.00
1	LHS CARRIER BOX BRACKET (SN)	SERVICEABLE	180.00	-
1	LHS TUBE CARRIER (SN)	CUT	68.00	68.00
			848.00	468.00
	<u>LABOUR</u>			
	TOWING.	NOT NECESSARY	40.00	-
	LABOUR CHARGE. INCLUSIVE OF THE REPAIR OF 1 SET FORK, BRAKE PEDAL AND LHS REAR FOOTREST BRACKET.		580.00	350.00
			620.00	350.00
	GRAND TOTAL		6,265.00	3,362.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,600.00

Report Ref No. CS/SMO21005810/Uqf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.