

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/GRB21005811/ABA3Q2
Date: 12/07/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SJG3171P	Insured Vehicle No :	SLW2422P
Date of Loss:	09/05/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002145

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG3171P	Engine No:	R16B25500893
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650JT000828
Reg. Date:	07/06/2018 (Man. Year: 2018)	Odometer:	83773 km
Colour:	Grey		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,514.72	2,260.96	1,253.76	35.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	630.00	1,680.00	72.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,824.72	2,890.96	2,933.76	50.37
Approved Total (Overridden) (S\$)		2,300.00		

(S\$)	5,824.72	2,300.00	3,524.72	60.51
+ GST 7.00/7.00% (S\$)	407.73	161.00	246.73	60.51
Nett Amount (S\$)	6,232.45	2,461.00	3,771.45	60.51
+ Car Rental (3.0 x S\$120.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,828.45		
Global Sum Settlement (S\$)		2,800.00		

INSPECTION

Date of Assignment: 11/05/2021

Date Inspected: 11/05/2021

Inspected At: MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre
Singapore 415933

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jun 2021)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJG3171P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	660.30 FL	*660.30 FL
2	1		*FRONT BUMPER SIDE RETAINER	N/S Damaged	124.80 FL	*35.40 FL
3	1		*FRONT BUMPER FOGLAMP COVER LH	Cut	80.00 FL	*80.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Dented	322.00 FL	*322.00 FL
5	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	160.20 FL	*- FL
6	1		*FRONT BUMPER INNER GARNISH LH	Deformed	90.00 FL	*90.00 FL
7	1		*CENTRE GRILLE	Cut	322.00 FL	*322.00 FL
8	1		*CENTRE GRILLE CHROME	Not Necessary	180.30 FL	*- FL
9	1		*CENTRE GRILLE H LOGO	Necessary	80.00 FL	*80.00 FL
10	1		*HEADLAMP LH	Cracked	1,120.60 FL	*1,120.60 FL
11	1		*HEADLAMP LOWER BRACKET LH	Cracked	65.90 FL	*65.90 FL
12	1		*FRONT FENDER LH	Not Necessary	580.30 FL	*- FL
13	1		*FRONT FENDER INNER COWLING LH	Not Necessary	189.20 FL	*- FL
14	1		*AIR CLEANER BOX ASSY	Not Necessary	280.30 FL	*- FL
15	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
16	1		*SET FRONT BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
17	1		*SET CENTRE GRILLE CLIP	Necessary	20.00 FS	*20.00 FS
18	1		*SET FRONT FENDER INNER COWLING CLIP	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,365.90	2,816.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	851.18	555.24
Total Parts (\$\$)	3,514.72	2,260.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING REMOVING AND REPLACE PARTS	New	1,000.00	400.00
2	SPRAY PAINTING TO AFFECTED AREAS	New	1,000.00	200.00
3	WIRING CHECK	New	60.00	30.00
4	TUFF COAT	New	250.00	0.00
Gross Labour Cost (\$\$)			2,310.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >