



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 9212R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT RH DOOR	DENTED	880.00	880.00
1	FRONT RH DOOR WEATHERSTRIPE	NOT NECESSARY	197.20	-
1	REAR RH DOOR	TO REPAIR SEE LABOUR	820.20	-
1	REAR RH DOOR WEATHERSTRIPE	NOT NECESSARY	185.20	-
1	ROCKER PANEL SIDE SKIRTING RH	NOT NECESSARY	528.30	-
1	ROCKER PANEL SIDE SKIRTING CLIPS	NOT NECESSARY	30.00	-
	LESS 15% DISCOUNT		-	-132.00
			2,640.90	748.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR RH DOOR.		800.00	300.00
	SPRAY PAINTING.		700.00	400.00
	WIRING.		50.00	30.00
	TO TRANSFER FRONT AND REAR DOOR FITTINGS.		300.00	80.00
			1,850.00	810.00
GRAND TOTAL			4,490.90	1,558.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,250.00

Report Ref No. CS/AGI21005817/Atf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.